

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

3a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Scarborough Estate
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 4
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>22S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat Tubb Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3324' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>P&A Blinebry Perfs</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with tubing. Set RBP at 5600', test 1000#. Drop 35' sand on RBP. Attempt to pump through perfs. If unable to pump through perfs, spot 200 gals 15% HCL 5506'-5395'. Set cement retainer at 5320', test tubing 3000#. Pump fresh water to establish injection rate. Pump 250 sacks Class "C" cement with CF-1. Squeeze 700#. Drop 4 sacks cement on cement retainer. Wait on cement 18 hours. Drill out cement and cement retainer, test squeeze. Circulate sand off RBP and POH. Equip well to pump in Tubb.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R D Pite TITLE Area Engineer DATE 2-23-83

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE

FEB 25 1983