Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

- Shake Clike		Revised 1.	1-89
P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVA	TION DIVISION		
P.O. Box 2088		WELL API NO.	
P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		30-025-20186	
DISTRICT III		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aziec, NM 87410		STATE	FEE XX
		6. State Oil & Gas Lease No.	-
SUNDRY NOTICES AND REPORTS ON	WELLS		m
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE APPLICATION FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE APPLICATION FOR THE DESCRIPTION FOR TH	EDEM OF SHIP SAME	7 1 1	
(FORM C-101) FOR SUCH PROPOSALS	IN DEBLITO	7. Lease Name or Unit Agreement Name	
1. Type of Well:	<u> </u>		
WELL WELL OTHER		77.	
2. Name of Operator		Vivian & Well No.	
Chevron U.S.A. Inc. 3. Address of Operator		a Well No.	
i -		9. Pool name or Wildcat	
P.O. Box 670, Hobbs, NM 88240		Blinebry Oil & Gas	
Unit Letter A 660 For Form			
Unit Letter A: 660 Feet From The North	Line and 660	Feet From TheEast	Line
Section 30 Township 22S	n 20m	·	
10. Elevation (Show wh	Range 38E N	MPM Lea	County
	·	· · · · · · · · · · · · · · · · · · ·	
11. Check Appropriate Box to Indic	ate Nature of Notice Re	mort or Other Date	
NOTICE OF INTENTION TO:	SLIDS	SEOUTH DEBOND	•
PERFORM REMEDIAL WORK		SEQUENT REPORT OF:	
- COSTAIND ABANDON	REMEDIAL WORK	XX ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	<u></u>	
PULL OR ALTER CASING	ı	- : EGG AND ABANDON	MENT
OTHER:	CASING TEST AND CEN	MENT JOB L	
	OTHER:	·	
 Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. 	is, and give pertinent dates in all its		
WORLY SEE ROLE 1103.	on personal dates, picture	ng estimated date of starting any proposed	
Work performed: 3/27/89 thru 4/1/89	TD: 5850 PB	5040	
	2020	- + 10	
Unseat pump. POH w/sucker rods. Hot oi	1 dn tbg. Strip ou	t 33 sucker rode DOU/	
Unseat pump. POH w/sucker rods. Hot oil dn tbg. Strip out 33 sucker rods, POH w/rods. POH w/prod. tbg. Tag CIBP at 5636'. C/O sand f/5636-5663. Tag CIBP at f/5808 to 5830 (scale) circ. clean. Porf 56/0.51 56/0.51 56/0.51 56/0.51			
f/5808 to 5830 (coals) size 1	er 2 hrs. Cleanout	to 5840'. Tight	
f/5808 to 5830 (scale) circ. clean. Perf 5648-51, 5656-61, 5665-71, 5684-90, 0° swab. TIH w/ 2 3/8" production the to 5822'. SW 8 5707!			
Swab. TIH w/ 2 3/8" production tbg. to Space out and hang off. Turn over to pro-	ris 5648-5812 w/4000	0 gallons 15% NEFE HCL.	
Space out and hang off. Turn over to pro	oduction	Run pump and rods.	
· · ·	Adde tion;		
I hereby certify that the information above is true and complete to the best of my knowledge	and belief.		
SIGNATURE L.K. Elmus	Technical Asst.		
e	mre Technical Asst.	DATE 4-4-89	
TYPE OR PRINT NAME (1997)	•		
(This space for State Use)		TELEPHONE NO.	
ORIGINAL SIGNED BY JERRY SEXTON			
APPROVED BYDISTRICT SUPERVISOR	<u>:</u>	ΔPR F K	1989
CONDITIONS OF APPROVAL IF ANY.	TITLE	DATE TILL	IUUJ

CONDITIONS OF AFFROVAL, IF ANY: