

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-023896
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name  CHRISTMAS
2. Name of Operator CAMPBELL & HEDRICK	8. Well No. 2
3. Address of Operator P. O. BOX 401, MIDLAND, TEXAS 79702	9. Pool name or Wildcat EUMONT YATES SEVEN RIVERS
4. Well Location Unit Letter <u>O</u> : <u>330</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>17</u> Township <u>22S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/17/00 Pull rods and pump. Tag bottom, tally tubing out of hole. Pick up work string and run to 3460, top perf, with perf clean tool. Treat to bottom perf, 3786, with 247 bbl KCl water. Rate 2.6 BPM, pressure 2220 to 2840. Acidize from bottom up with 2000 gal 15% HCl. Rate 2.4-2.7 BPM, pressure 2200-2600 psi. Circulate hole clean. Pull and lay down work string. Run tubing. Swab. Run pump and rods to 3750'.

9/16/00 Pump 5.7 BO, 33.3 <sup>mcf</sup> and 31BWPD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE O. F. Hedrick TITLE OPERATOR DATE 9/18/00

TYPE OR PRINT NAME O. F. HEDRICK

TELEPHONE NO. 915-684-4

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: