

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

API # 30-025-24380

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
P-33440

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Phillips Petroleum Company

Address of Operator
Room 401, 4001 Penbrook, Odessa, Texas 79762

Location of Well
UNIT LETTER C 380 FEET FROM THE north LINE AND 2310 FEET FROM
THE west LINE, SECTION 24 TOWNSHIP 22-S RANGE 37-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Sims

9. Well No.
7

10. Field and Pool, or Wildcat
Undesignated

15. Elevation (Show whether DF, RT, GR, etc.)

3226' GR, 3337' RKB

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☒

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER Deepen ☒

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Continued from report dated 2-11-83:

2-21-83: MI Barber WSU. Ran flat btm mill 1- -4-1/2" DC, jars, 6--3-1/2" DC's on 175 jts of 2-7/8" N-80 tbg.

2-22 thru 3-2-83: Milling.

3-3 thru 3-13-83: Washing over tbg.

3-14-83: POOH. Milled from 5862'-5865'. 3' of progress, mill quit. POOH. Rec 11' of tbg & junk. Milling shoe tagged fill @ 5635'. Milled 2 hrs.

3-15-83: Fishing.

3-16, 17-83: SD for high winds.

3-18-83: TIH. WIH & washed over from 5845'-5855', shoe jammed. POOH, recovered 18-1/2' of tbg.

3-19, 20, 21-83: Washed from 5882', made 39'. Circd hole clean.

3-22, 23, 24-83: Milling.

See Reverse Side.

BOP Equip: Series 900, 3000# WP, double w/one set pipe rams, one set blind rams, manually operated

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] W. J. Mueller TITLE Sr. Engineering Specialist DATE June 23, 1983

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE JUN 28 1983

3-25, 26, 27-83: 25th POOH, rec 6' of 2-3/8" tbg. W/ new shoe, washed over from 5957' - 5972', 13' of progress. 26th, milling-6' of progress. Shoe jammed, started out of hole & SD due to high winds. 28th, COOH, no recovery. W/ new shoe, milled from 5978'-5980', 2' of progress, shoe jammed, POOH, rec. 12' of tbg.

3-28-83: POOH. W/ flat btm mill & milled from 5976'-5985', 9' of progress. Started out of hole.

3-29-83: Washing over; W/ milling shoe & washed over pipe. Washed over from 5985'-6030', 45' of progress.

3-30-83: Washing over. Washed over from 6030'-6032' & shoe quit. POOH & ran new shoe. Washed over from 6032'-6053'. 21' of progress.

3-31 thru 4-3-83: 31st, washed over from 6053'-6071', 18' of progress. 1st, washed over from 6071'-6162'. Dropped out of cmt @ 6130', POOH no rec. 2nd, W/ outside cutters. Got over 1st jt, could not get over 2nd, jt & could not make cut. POOH. 3rd, dwn 24 hrs--crew off.

4-4-83: W/ overshoot w/ 2-19/32 slips tagged fish @ 6066'. COOH & rec 13' of tbg. W/ overshoot w/ 3-1/16 slips, did not catch fish.

4-5-83: W/ overshoot w/ 2-19/32" slips latched onto fish, rec. 4' of junk. W/ overshoot & 2-3/8" slips & latched onto fish, rec'd 774' of tbg & junk.

4-6-83: W/ overshoot w/ 2-3/8" slips, tag fish @ 6865'. POOH, rec'd 14" of tbg slivers. W/ 60 stands.

4-7-83: Dwn 24 hrs--snowing.

4-8, 9, 10-83: Fishing. GIH w/ overshoot. 8th, W/ overshoot, tagged fish @ 6865', no progress, POOH. 9th, W/ flat btm mill, milled from 6870'-6873', POOH. W/ overshoot & latched onto fish, POOH. 10th, POOH w/ overshoot & rec'd small piece of junk. W/ cutrite shoe on 1 jt of wash pipe. Washed from 6873'-6877', fish fell free. Washed over to 6909'. POOH, rec. 4' of junk.

4-11-83: Latched onto fish @ 6874'. Jarred on fish 2-1/2 hrs, jars quit. Rel overshoot & POOH.

4-12-83: W/ 300' of wash pipe w/ cutrite shoe. Wash over fish to 6173'. Circd hole clean. Started out of hole.

4-13-83: TIH w/ overshoot. Catch fish @ 6874'. Jar fish loose. POOH. Rec. stringer, 9 jts tbg.

4-14-83: TIH w/ Kelvin's bailer. CO to 7163'. POOH. Rec. small amount of junk. GIH w/ pkr. Set @ 5900'. Test tbg-csg annulus to 1000 psi for 10 min. Hold OK. GIH w/ pkr @ 6346'. Test Tubb perfs dwn tbg-csg annulus to 1000 psi for 10 mins. OK. RU on tbg, established injection rate on Drinkard perfs, 8/10 BPM, 1000 psi. Rel pkr. POOH.

4-15, 16, 17-83: 15th, W/ Howco retainer, set @ 6375'. Tstd tbg to 2500#, OK. Press backside to 1000#, OK. Sqzd 97 sx cmt into perfs from 6415' to 7114' w/ hesitation sqz to 1800#. Pld out of ret, rev hole clean. Circd 3 sx cmt & POOH. 16th, W/ bit & DC's, tagged cmt ret @ 6376'. Dld ret & 10' of cmt, cmt not set up. Rev hole clean. Pld 3 stds & SD. 17th, dwn 24 hrs--crew off.

4-18-83: GIH w/ 3 stands. Dld 6380'-6720', 340' progress. Circd hole clean. Pld 1 stand.