

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other Instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A.H. Blinebry Fed. NCT-1

9. WELL NO.

38

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 19, T-22-S, R-38-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface1980' from South Line, 1980' from East Line, Section 19,
Township 22-S, Range 38-E, Unit Letter 'J', Lea County,
New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, FT, GR, etc.)

3358' (GR)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. Perforate 7" OD Liner w/2 JSPF @ 6316', 6324', 6333', 6344', 6354', 6362', 6370', 6380', 6386', 6404', 6414', 6427', 6433', 6440', 6464', 6472', 6492', 6505', 6518', 6585', 6597', 6603', 6609', 6615', 6620', 6625', 6632', 6640', 6664', 6679', 6685', 6700', 6711', 6723', 6741', 6751', 6777', 6907', 6915', 6930', 6941', 6960', 6986', 7005', 7023', 7033', 7040', 7046', 7060', 7070', 7101', 7110'.
2. Ran 2-7/8" tubing w/packer and set @ 6892'.
3. Acidize perforations 6907'-7110' w/2000 gals. 15% NEA w/45 ball sealers.
4. Frac w/20,000 gals. Poly-Vis III w/1-2# 20-40 sd/gal. in 4 stages w/total 1850 lb. RS & BAF between stages.
5. Move RBP from 7141' & reset @ 6892'. Set packer @ 6278'.
6. Acidize perfs. 6316'-6777' w/4000 gals. 15% NEA w/100 ball sealers.
7. Frac perforations 6316'-6777' w/40,000 gals Poly-Vis III w/1-2# 20-40 sand/gal. in 8-5000 gal. stages w/total 5300# RS & BAF between stages.
8. Flush w/55 bbls fresh water.
9. Reset RBP @ 7141' and packer @ 6278'.
10. Swab.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Asst. District Supt.

DATE

10-31-75

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

