

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 032369

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Elliott B-12

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Drinkard

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 12, T-22-S, R-37-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3350 GR

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Reset Packer & test

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

REPAIRING WELL

☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. RU slick-line unit, set blanking plug in on-off tool
2. MIRUPU. Kill Drinkard zone with 2% KCl water containing 1 gal./1000 Western's LT-22.
3. Unlatch and pull short string. Release dual packer and pull long string.
4. (a) Redress (or change out) Otis dual hydraulic packer.
(b) Run long string with dual packer spaced out to land at 6400' (+). On short string side, dual packer is to have a 2-3/8" "N" nipple with a 1.791" No-Go, ball catcher sub, and a bull plugged perforated pup joint. Space out and set into perma-Latch. Test long string to 1000 psi.
(c) Run short string (will need an additional 300' of 2-3/8" w/beveled collars) with seal and latch-in assembly on bottom and with an Otis Model "XA" 2-3/8" sliding side-door (sleeve) one joint above bottom. Space out and latch into dual packer. Set hydraulic packer and put 12,000# on it.
(d) Nipple up dual wellhead. RDMOPU, RU swab unit.
5. Swab fluid level in long string to 4000' from surface. RU slick-line unit and pull blanking plug from long string. Open long string and flow back load. Run blanking plug into short string and set into "N" nipple, open sliding sleeve, RD slick-line unit, and swab upper Drinkard perforations to flow and recover load.
6. RU slick-line unit. Close sliding sleeve and pull blanking plug. RD slick-line unit. Swab test lower Drinkard perforations.
7. (a) If swab test is encouraging (as to fluid entry) set a test pumping unit to recover load and test.

(Continued on back)

18. I hereby certify that the foregoing is true and correct

SIGNED

W. J. McIntire

TITLE

Area Superintendent

DATE

6-14-76

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUN 18 1976

BERNARD MOROZ
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

G.P.O. : 1973- 780-622 /VIII- 148

7. (b) If swab test indicates little fluid entry, treat lower Drinkard perforations with 5000 gals. Western's Dolowash (7-1/2% Acid w/de-emulsifiers). Flush Dolowash with 2% KCl water containing 1 gal./1000 LT-22. Dolowash and flush is to contain 500 SCF/Bbl. Nitrogen. Pump Dolowash at 5 BPM, not exceeding 5000 psi and have at least 1300 psi built up on backside from upper Drinkard perforations. Swab test lower Drinkard perforations, setting a test pumping unit to recover load and test if swabbing indicates sufficient fluid entry.
8. Produce upper Drinkard perforations up the tubing-casing annulus and lower Drinkard perforations up the short string.

RECEIVED
JUL 1 1973
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
DENVER, COLORADO