

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Anadarko Production Company	8. Farm or Lease Name M.W. Coll
3. Address of Operator P.O. Box 806 Eunice, New Mexico 88231	9. Well No. 4
4. Location of Well UNIT LETTER <u>K</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Langlie Mattix - Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3313' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Perf additional Penrose &amp; acidize &amp; frac.</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- RUPU, TOH w/rods & tbg.
- Perf additional Penrose @ 3544' - 3550' - 3559' - 3565' w/2 JSPF.
- TIH w/RBP & Pkr on 2-7/8" tbg. Acidize new perfs w/1,000 gals 15% NEFE acid. TOH w/RBP & Pkr.
- TIH w/Pkr & 2-7/8" tbg. Set Pkr @ 3460'.
- Frac w/36,000 gals gelled 2% KCL w/65,000# 20/40 sand & 30,000# 10/20 sand. SI for night.
- Release Pkr. Wash sand to PSTD 3754'. TOH w/ Tbg & Pkr.
- TIH w/ Tbg, pump & rods. POP, RDPU.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Foreman DATE March 28, 1983  
APPROVED BY ORIGINAL SIGNED BY EDDIE SEAY TITLE \_\_\_\_\_ DATE MAR 30 1983  
OIL & GAS INSPECTOR  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

RECEIVED  
MAR 29 1983  
HOBBS OFFICE