

WORKOVER PROCEDURE

DATE: 3/15/90

WELL & JOB: SRQU # 58 PLUG AND ABANDON

DRILLED: 1983

LAST WORKOVER: 1987

FIELD:

COUNTY: LEA

BY: GORE

TD: 3925

PBD: 3881

DATUM: RKB = 12'

TUBINGHEAD:

SIZE:

PRESS RATING:

CASING:	<u>SIZE</u>	<u>WEIGHT</u>	<u>GRADE</u>	<u>SET @</u>	<u>SX CMT</u>	<u>TOC</u>
SURFACE:	8-5/8"	24#	K-55	312'	300	SURFACE
INTER:						
PROD:	5-1/2"	15.53	K-55	3925'		SURFACE

PERFORATIONS: 3695'-3849'

TUBING:	SIZE: 2-3/8"	WEIGHT: 4.7	GRADE: J-55	THREAD: EUE
BTM'D @ 3825		JOINTS: 122	MISC: TAC	

SCOPE OF WORK: PLUG AND ABANDON

PROCEDURE

1. MIRU PU. LAY DOWN RODS AND PUMP.
2. NU BOPE. AND PULL CA.
3. SET CIBP @ ^{3630'} 3830' AND CAP W/ 35' CEMENT.
4. LOAD AND TEST CASING TO 500 PSI.
5. TIH W/ OPEN ENDED TUBING TO 3750 AND CIRCULATE HOLE W/ 9.5 PPG MLF.
6. POOH AND SPOT PLUGS AS FOLLOWS:
 - a. 100' CEMENT PLUG 3100'-3000'
 - b. 100' CEMENT PLUG F/ 1505'-1405'
 - c. 100' CEMENT PLUG F/ 362'-262'
 - d. 30' CEMENT PLUG F/ 30'-0
7. ND BOPE AND CUT OFF WELLHEAD. WELD ON STEEL PLATE W/ VALVE

M. W. Gore

Concur:

RDR
R. D. Reynolds

J. E. Shields