ENERGY AND MINERALS DEPARTME		
	OIL CONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-103
SANTA PE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
PILE	4	Sa. Indicate Type of Leuse
U.3.0.8,	4	State Fee X
LAND OFFICE	4	
OPERATOR)	5, State Oli & Gas Lease Na.
SUNDR	RY NOTICES AND REPORTS ON WELLS PASALS TO DAILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
1.		7. Unit Agreement Name
	07 H ER -	
2. Name of Operator		8. Farm or Lease liame
Marathon Oil Com	J. L. Muncy	
J. Address of Operator	9. Well No.	
P. O. Box 2409	4. well No. 6	
4. Location of Well	Hobbs, NM 88240	
		10. Field and Pool, or Wildcat
UNIT LETTER I	330 FEET FROM THE East 1920 FEE	Blinebry
THE SOUTH LINE RECTO	DH 24 TOWNSHIP 225 RANGE 37E	
	// RANGE	. MM PM. (()()()()()()()()()()()()()()()()()()(
anna an	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	GL 3323, KB 3335	Lea
Check A	Appropriate Box To Indicate Nature of Notice, Report of	or Other Data
NOTICE OF IN		UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ASANDON	COMMENCE DRILLING OPHS.	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
		ions & stimulate
OTHER		(°.)
17. Describe Proposed or Completed Ope	erations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any proposed

ug any proposed work) SEE RULE 1103.

On October 31, 1985, perforations were added to the Blinebry zone at 5511, 20, 28, 37, 43, 46 with 1 JSPF (6 holes). A retrievable bridge plug was set at 5556' isolating these new perforations from the existing ones at 5564'-5820'. These new perforations were then acidized with 500 gallons of 15% HCl. Then they were fraced with 15,000 gallons of Pur-Gel 30 containing 25,000# 20/40 sand. After swab testing for a few days, the RBP at 5556' was pulled out of the hole. The longstring was run back into the hole and was latched into a parallel anchor at 5820'.

On November 9, rods and pump were run in the shortstring to pump the Plinebry zone. The well is presently being pump tested. The lower Tubb gas zone is still shut in.

Eddie W. Sedy Oil & Gas Inspector			NOV 2 5 1985
\$16#ED	Thomas F. Zapatkal Thomas F. Tapatkal	Production Engineer	<u>11-20-85</u>
	certify that the information above is true and complete to the be	-	