to Appropriate District Office	End 	ergy, Minerals an	d Natural Resources De	epartment		Form C-103 Revised 1-1-8
DISTRICT I P.O. Box 1980, Hobbs, NM 8	9340 O	CONSEI	RVATION DIV	ISION	WELL API NO.	
DISTRICT II	6240	P.0	O. Box 2088		30-025-29975	
P.O. Box Drawer DD, Artesia,	NM 88210	Santa Fe, N	ew Mexico 87504-20	088	5. Indicate Type of Lease	
DISTRICT III					STATE [FEE 🔽
1000 Rio Brazos Rd., Aztec, N					6. State Oil / Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI					7. Lease Name or Unit Agreement Na	ame
	(FORM C-101)	FOR SUCH PRO	POSALS.		AMANDA	
1. Type of Well: OIL WELL	GAS WELL	OTHER				
Name of Operator Ch	HEVRON USA INC				8. Well No.	
Address of Operator 15 Well Location	SMITH ROAD, M	IDLAND, TX 797	05	 -	Pool Name or Wildcat BLINEBRY OIL AND G.	`AC
					DEINEBRY OIL AND G	AS
Unit Letter (D:330'_	Feet From T	he SOUTH Line and	1650'	Feet From The EAST Li	ine
Section 25	Towns	ship 22-S	Range <u>37-E</u>	NM	PM LEA CO	UNTY
	10. EI	evation (Show wheth	ner DF, RKB, RT,GR, etc.)	3324' KB		
11.	The state was in					
NOTICE OF IN			icate Nature of Notic			
PERFORM REMEDIAL WORK					BSEQUENT REPORT OF	F:
TEMPORARILY ABANDON		ND ABANDON E PLANS	REMEDIAL W		ALTERING CASING	
PULL OR ALTER CASING		EFLANS		DRILLING OPE		IMENT
	ADD PERFS & ACID	17F		AND CEMENT	JOB	
CHEVRON U.S.A. INTENDS T THE INTENDED PROCEDURE	O ADD PERFS IN	THE BLINEBRY	FORMATION AND ACID	IZE THE SUB	es, including estimated date of star BJECT WELL. GRAM IS ATTACHED.	tung uny
,	; ₇ 7					
		ρ				
I hereby certify that the information above is true an	d complete to the best or my	Dowledge and belief.				
SIGNATURE J. W.L.	111000 711	TITLE	Regulatory Specia	list	DATE3/21/20	002
TYPE OR PRINT NAME	Denise Lea	ıke			Telephone No. 915	-687-7375
(This space for State Use)						
APPROVED		ÚKI	GINAL AL		Mic	
B WINDITIONS OF APPROVAL, IF AN	<u> Y:</u>	LE	GINAL SIGNED BY	•	MAR 2 6 2002	
		PETR	OLEUM ENGINEER		DeSoto/Nichols 12-93 ver 1.	.0
			" LINGINEER			

Amanda # 3 Blinebry Oil & Gas Field T22S, R37E, Section 25 Job: Add Perfs In Blinebry Formation And Acidize

Procedure:

- 1. MI & RU pulling unit. Bleed pressure from well, if any. Pump down csg with 2% KCl water containing 2 GPT BJ Inflo 150 fluorosurfactant, if necessary to kill well. POH with rods and pump. Remove WH. Install BOP's and test to 1000 psi. Note: All 2% KCl water used is to contain 2 GPT BJ Inflo 150 fluorosurfactant.
- 2. POH with 2 3/8" tbg string.
- 3. PU and GIH with 4 ¾" bit on 2 7/8" work string to top of Watson scab liner at 2807'. Reverse circulate well clean from 2807' using 2% KCl water. POH with 2 7/8" work string and bit. LD bit.
- 4. PU retrieving tool for Watson scab liner pkr, DC's, and bumper jars and GIH on 2 7/8" work string to 2807'. Engage scab liner at 2807'. Release liner pkrs and POH with Watson scab liner. LD scab liner assembly. Note: Report condition of 4 ½" csg and liner pkrs. If severely corroded, external coating may be required before re-installing.
- 5. PU and GIH with 4 3/4" bit on 2 7/8" work string to approximately 5800'. Reverse circulate well clean from 5800' using 2% KCl water. POH with 2 7/8" work string and bit. LD bit.
- 6. PU 5 ½" RBP and pkr and GIH on 2 7/8" work string to approximately 5300'. Set RBP at 5300' and test to 500 psi. PUH with pkr to 2950'. Pressure test casing from 2950-5300' to 500 psi. PUH with pkr to 2800'. Pressure test casing from 2800'- surface to 500 psi. Note: If casing fails either pressure test, pinpoint leak using pkr and RBP.
- 7. LD and engage RBP at 5300'. POH with 2 7/8" work string, pkr, and RBP. LD pkr and RBP.
- 8. MI & RU electric line unit. Install lubricator and test to 1000 psi. GIH with 3 1/8" DP slick casing gun and perforate from 5366-70', 5390-5402', 5414-20', 5430-42', 5464-70', 5496-5510', 5528-36', 5557-59', 5564-67', 5571-75', 5583-90', 5594-5602', 5612-16', and 5630-36' with 4 JSPF at 120 degree phasing, using 23 gram premium charges. POH. RD & release electric line unit.
- 9. PU and GIH w/ 5 ½" treating pkr on 2 7/8" work string, testing to 6500 psi. Set pkr at approximately 5250'. Fill annulus and monitor for communication during acid job.
- 10. MI & RU BJ Services. Pump down 2 7/8" tubing and acidize perfs 5366-5636' with 9,600 gals 15% anti-sludge HCl acid ** at a pump rate of **8 BPM** and a maximum treating pressure

of **6500** psi. Drop 575 - 1.1 sp. gr. 7/8" ball sealers evenly distributed throughout treatment. Displace acid with 2% KCl water containing 2 GPT BJ Inflo 150 fluorosurfactant -- do not overdisplace. Record ISIP, 5, 10, & 15 minute SIP's.

Note: Pickle tubing in 2 runs of 250 gals acid each, prior to acidizing perfs. Pickle acid is to contain only 1/2 gal CI-25 and 1 gal NE-13.

** Acid system is to contain:

1 GPT CI-25

Corrosion Inhibitor

2 GPT FE-270L

Iron Control

1 GPT FE-271L

Iron Control Catalyst

25 GPT US-40

EGMBE

2 GPT Inflo 150 1 GPT FAW-18

Fluorosurfactant Binding Agent

1 GPT NE-13

Non-Emulsifier

- 11. Release treating pkr and LD to approximately 5650' to wipe balls off perfs. PUH to 5300' and set treating pkr. Swab back all intervals together. Recover 100% of treatment and load volumes before shutting well in for night. Report recovered fluid volumes, pressures, and/or swabbing fluid levels.
- 12. Open well. Pump down tbg with 2% KCl water containing 2 GPT BJ Inflo 150 fluorosurfactant to kill well. Release pkr. POH with 2 7/8" work string and trtg packer. LD pkr.
- 13. PU and GIH with redressed Watson scab liner assembly (top and lower pkrs with 250' of 4 ½" 11.35# FL4S casing in between). Set Watson scab liner assembly with lwr pkr at approximately 3000' and upper pkr at approximately 2750'. Release from Watson scab liner assembly. POH with 2 7/8" work string and Watson retrieving tool. LD 2 7/8" work string and retrieving tool.
- 14. PU and GIH w/ BP mud anchor jt of 2 3/8" tbg, 2 3/8" x 4' perforated sub, SN, and 183 jts 2 3/8" EUE 8R J-55 tbg, testing to 5000 psi. Hang tbg with EOT suspended at 5700' and SN at 5665'.
- 15. Remove BOP's and install WH. GIH with rods, weight bars, and pump per ALS recommended design. RD & release pulling unit.
- 16. Turn well over to production. Report producing rates and fluid levels.

AMH 3/19/2002



