Suhmit 3 copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department	Form C-103 Revised 1-1-89					
DISTRICTI	OIL CONSERVATION DIVISION	WELL API NO.					
P.O. Box 1980, Hobbs, NM 88240 DISTRICT II	P.O. Box 2088	30-025-32909					
O. Box Drawer DD. Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease					
DISTRICT III	STATE FEE						
1000 Rio Brazos Rd., Aztec, NM 8741		 State Oil / Gas Lease No. NM-18848 					
SUNDRY NO							
(DO NOT USE THIS FORM FOR PR DIFFERENT RESI	7. Lease Name or Unit Agreement Name						
(FORM	SDE '19' FEDERAL						
1. Type of Well: OIL GAX WELL WE	-						
2. Name of Operator	8. Well No.						
Texaco Ex	-						
3. Address of Operator P. O. Bo:	9. Pool Name or Wildcat SAND DUNES BONE SPRINGS.SOUTH						
4. Well Location							
Unit Letter K	2180 Feet From The SOUTH Line and 2310	Feet From The WEST Line					
Section 19 Township 23-S Range 32-E NMPM LEA COUNTY							
	10. Elevation (Show whether DF, RKB, RT,GR, etc.) GR-36	14', KB-3628'					
^{11.} Check A	Appropriate Box to Indicate Nature of Notice, Repo	ort, or Other Data					
NOTICE OF INTENTI	SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING					
	CHANGE PLANS COMMENCE DRILLING OPE	COMMENCE DRILLING OPERATIONS PLUG AND ABANDONMENT					
PULL OR ALTER CASING	CASING TEST AND CEM	CASING TEST AND CEMENT JOB					
	OMPLETE OTHER:						

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE ATTACHED PROCEDURE

5 U

I hereby certify that the information above is truggand complete to the best of my kr SIGNATURE	nowledge and belief. TITLE Engineer	DATE 7/19/2001
TYPE OR PRINT NAME JASM Wack		Telephone No. 9156884862
(This space for State Use)	Drig Eligned D. Paul Naul2 Geologist	ANN O A SAMA
APPROVED BONDITIONS OF APPROVAL, IF ANY:TIT	Goologist	DATEDeSolo/Nichols 12-93 ver 1 0
		and the second

• 5

H Jason Wacker Production Enginee: Deriver Division Hobbs Operating Unit



Texaco Exploration and Production Inc Production file PO Pix 2009 5% N Loraine Michand TX 79702 Office 915 688 4862 Temper 672 4862 Fermer 915 699 5343 En pix 1 200 413 4684 proceed

E-mail: wackehj@texaccurces

no voore Decisientuapen 🖨

7/19/2001

SDE 19 Federal #4 2180' FSL & 2310' FWL, K-19-23S-32E Lea County, New Mexico

Delaware Re-Completion

Well Data

Tubing:	2-7/8"	Casing:	Casing: 5-1/2", 15.5# & 17#, L-80 & K-55 @ 9850'			
TD:	9850'	PBTD:	9706	Elevation:	3614' GL	14' KB
Open Perfor	rations:					
Bone Spring	ž	8630' - 86	52' w/ 2 spf			

Procedure

- Rig up pulling unit. Purchase and set pipe racks. TOH with pump & rods. Call Unichem, Jerry White, and Axelson, John Dimock, prior to getting pump out of hole. Inspect pump and rods for scale and paraffin, collect samples.
- 2. ND wellhead. NU BOP. TOH with production tubing, tubing anchor, and MHMA. TIH with bit and scraper on 2-7/8" production tubing to 8600'. TOH with bit and scraper.
- 3. Notify NMOCD prior to plugging back Bone Spring.
- 4. Rig up Schlumberger. Set CIBP at 8580' with 35' cement on top. Rig down Schlumberger.
- 5. TIH with a 5-1/2" X 2-7/8", 15.5# 17# full bore treating packer on 2-7/8" production tubing. Load hole with corrosion inhibited half-and-half brine water. Set packer at 8480'. Pressure test CIBP to 500 psig for 30 minutes with kill truck. Scanalog production tubing out of hole. Send junk tubing to warehouse. Lay down and rack all but 5500' of yellow band production tubing.
- 6. Rig up Schlumberger. Perforate the Delaware interval (5330' 5340') with 4 spf. Rig down Schlumberger.
- 7. TIH with purge valve, 3-1/2" MHMA, SN, and 2-7/8" production tubing with tubing anchor. Set tubing anchor at +/- 5250'. Set SN at 5500'. Run 12' gas anchor, 1-3/4" Panacea pump, and grade EL sucker rods with T grade couplings. Set pumping unit to run 8 SPM in the 144" hole.
 - 86 7/8" Rods
 - 124 3/4" Rods
 - 10 1-1/2" Sinker Bars

5500'

- Return well to production. RD pulling unit. Have Unichem treat for corrosion, paraffin.
 & barium sulfate scale (precautionary). Evaluate for completion fracture stimulation.
- 9. File status change to show well was re-completed from the Sand Dunes Bone Spring, South pool to the Triste Draw Delaware, West pool.