

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-025-33794
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	A. B. Baker
8. Well No.	6
9. Pool name or Wildcat	Wantz Granite Wash

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Collins & Ware, Inc.	
3. Address of Operator 508 West Wall, Suite 1200, Midland, Tx 79701	
4. Well Location Unit Letter <u>I</u> : <u>2135</u> Feet From The <u>South</u> Line and <u>829</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>22S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3385' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/21/97 TD reached at 4:45 AM at 7220'.

2/22/97 Ran Platform Express Logs.

2/23/97 Ran 5 1/2" 17# and 15.5# casing to 7220'. DV tool at 4238'. Cement with 1680 sx cement. Circulate 33 sx cement to pit. Release rig.

3/10/97 PBTD at 7159'. Pull GR/CCL/CBL from PBTD to 3000'.

3/11/97 Perforate Granite Wash from 7052' - 7073' with 19 holes. Set packer at 6977' and acidize perms (7052' - 7073') with 2500 gals 7.5% HCL acid. Pump 1000 SCF Nitrogen with all fluids. Flush with 60,000 SCF Nitrogen.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Supervisor DATE 3/17/97

TYPE OR PRINT NAME Dianne Sumrall

TELEPHONE NO. (915) 687-3435

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

MAR 25 1997

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY