

COPIES TO BE RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-7

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☐ OTHER: Storage Well

2. Name of Operator  
Warren Petroleum Company *Green Oil Corp.*

3. Address of Operator  
Box 1197 - Eunice, New Mexico 88231

4. Location of Well  
UNIT LETTER *2 G* 1887 FEET FROM THE north LINE AND 1320 FEET FROM  
THE east LINE, SECTION 3 TOWNSHIP 22S RANGE 37-E NMPM.

7. Unit Agreement Name  
*Mark LPG*

8. Farm or Lease Name  
Eunice Plant #161

9. Well No.  
LPG #2

10. Field and Pool, or Wildcat  
Mark

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Pump 100 barrels fresh water down casing string.
- Move in and rip up pulling unit. Pull 2 7/8" tubing out of hole.
- Run bit and scraper on 2 7/8" rental tubing to 1450' depth. Pull out of hole.
- Run cast iron bridge plug in hole on 2 7/8" rental tubing. Set bridge plug at 1400'.
- Spot 100' cement plug on top of C.I.B.P. Pressure 5" casing to 500# for thirty minutes circulating hole with abandonment mud.
- Pull tubing to required depth to spot second plug, approximately 490'.
- Pump 100' to 400' of cement for second plug.
- Spot 50" to 100" surface cement plug. Install marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *C. D. Hansen* TITLE Plant Manager DATE 6-12-80

APPROVED BY *James L. Hansen* TITLE SUPERVISOR DATE 1980

CONDITIONS OF APPROVAL, IF ANY:

FROM C. D. Flowers

AT Eunice

IN REPLY  
REFER TO

TO M. L. Ingram

AT Tulsa

DATE 9-26-79

SUGGESTED PROCEDURE TO PLUG AND ABANDON THE #1 PRODUCT STORAGE  
WELL LOCATED AT THE EUNICE, NEW MEXICO PLANT

- 1) Pump 100 barrels of fresh water down casing string
- 2) Move in and rig up pulling unit. Pull 4 1/2" tubing out of hole
- 3) Run bit and scraper on 2 7/8" rental tubing to 1450' depth. Pull out of hole.
- 4) Run cast iron bridge in hole on 2 7/8" rental tubing. Set cast iron bridge plug at 1400'. Pull tubing out of hole.
- 5) Pump 100' cement on top of bridge plug.
- 6) Spot cement 100' below surface casing approximately 490' from surface. Pump 100' to 400' of cement. This will be decided on location depending on casing condition when work is done.

CDF:rs

Xc: Clint Morrill  
Gulf Oil Corporation  
Hobbs, New Mexico