

WORLDWIDE ENERGY CORPORATION

MOSLEY # 1 - JALMAT FIELD

Lea County, New Mexico

WORKOVER PROGNOSIS-PLUG and ABANDON

1. Move in and rig up service unit.
2. Tally tubing. Run in hole with tubing, bit sub and bit.
3. Rig up power swivel, reverse unit, etc. Drill out CIBP at 750'. Clean out casing to parted casing point at 1520'±.
4. Run in hole with impression block.
5. Based on impression block it may be necessary to go in hole with mill and mill off casing stub prior to attempting getting into lower casing stub.
6. Use swedges, jars, etc. as needed to line up casing.
7. After lining up casing run in hole with tubing string to 3500'.
8. Spot 25 sack cement plug at 3500'.
9. Pull out of hole with tubing to 1520'. Spot 50 sack cement plug across parted casing stub.
10. Pull out of hole with tubing. Place 5 sack plug at surface.
11. Cut off casing 3' below surface. Weld plate on. Attach surface marker to plate.

TCH/ba
3/2/81