

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
-----	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name <b>Skelly Penrose "A" Unit</b>
2. Name of Operator <b>Skelly Oil Company</b>	8. Farm or Lease Name <b>Skelly Penrose "A" Unit</b>
3. Address of Operator <b>P. O. Box 1351, Midland, Texas 79701</b>	9. Well No. <b>22</b>
4. Location of Well UNIT LETTER <b>E</b> , <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>3</b> TOWNSHIP <b>23S</b> RANGE <b>37E</b> NMPM.	10. Field and Pool, or Wildcat <b>Langlie-Mattix Penrose Sd</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3308' DF</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER <b>Clean out and repair casing leak</b> <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Move in workover rig. Pull Rods and tubing.
- 2) Set retrievable bridge plug at 2000' and cap with 7 sacks sand and fill hole with water back to 1398' and check for additional leaks.
- 3) Cement squeeze holes in 7" OD casing at 72' and 1398' with 200 sacks Class "C" cement. WOC.
- 4) Drill out cement and test for additional leaks.
- 5) Clean out sand cap and recover retrievable bridge plug. Clean out gravel in well bore from 3544' to 3620'.
- 6) Return well to production status pumping Penrose Sand open hole 3410-3650'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(Signed) **D. R. Crow** **D. R. Crow** TITLE **Lead Clerk** DATE **7-23-74**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: