

OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER- Water Injection	7. Unit Agreement Name Skelly Penrose "A" Unit
2. Name of Operator Skelly Oil Company	8. Farm or Lease Name Skelly Penrose "A" Unit
3. Address of Operator P. O. Box 1351, Midland, Texas 79701	9. Well No. 28
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 3 TOWNSHIP 23S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Langlie-Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3303' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER Eliminate waterflow in annulus behind 7" OD casing. <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Move in workover rig. Pull tubing.
- 2) Perforate 7" OD casing with two shots at 2500'.
- 3) Set retrievable bridge plug at approximately 3000' and cap with sand.
- 4) Cement behind 7" OD casing to eliminate waterflow.
- 5) Test squeezed 7" OD casing and resqueeze perfs., if necessary.
- 6) Pull retrievable bridge plug and clean out to 3610'.
- 7) Return well to injection status injecting through Queen open hole 3408-3610'.

NOTE: Waterflow is between 10-3/4" OD and 7" OD casing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signed) D. R. Crow D. R. Crow TITLE Lead Clerk DATE 10-7-74

APPROVED BY Signed By TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: