STATE OF NEW MEXICO

ENERGY	A 8/73	MINIEDALS	DEPARTMENT
CINCHOL	ANO	WILLELING?	DEPARTMENT

wa. er .geite acttives	_
DISTRIBUTION	_
SANTA FE	_
FILE	
U.S.G.S.	
LAND OFFICE	_
OPERATOR	_

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501 0+6 - NMOCD-P.O. Box 1980

Form C-103 - Revised 10-1-

.... DEC 3 0 1983

Dala B Crackett	
Della het me Area Superintendent	
ntinued onback)	
Tag top of cement and drill out cement. 24 HOURS PRIOR TO COM	MENCING WORK
GIH with bit, drill collars, and workstring CCMMISSION MUST	BE NOTIFIED
WOC.	
determined by Halliburton based on dye results.	
last 2-3 bbls. of cement. POH with packer. Specific volumes to	
-	
	on RRP
	ın /" csg.
	7.11
cribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, included () SEE RULE 1103.	fing estimated date of starting any propo
OTHER	
CHANGE PLANS CASING TEST AND CEMENT JOB	
	PLUG AND ABANDONMENT
M REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
NOTICE OF INTENTION TO: SUBSEQUE	ENT REPORT OF:
Check Appropriate Box To Indicate Nature of Notice, Report or	Other Data
	Lea \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
West Line, Section 4 Township 23-5 MANGE 37-E	PM. (
C 660 PEET FROM THE North LINE AND 1980 FEET FO	Langlie - Mattix
	10. Field and Pool, or Wildcat
	18
	Skelly Penrose A Un
	8. Farm or Lease Name
C TITLE WELL LA OTHER-	
	7. Unit Agreement Name
- (DO NOT VIETNIE PORM FOR PROPOSALS TO DRILL OR TO OFFPEN OR PLUG FACE TO E DIFFERENT RESTRUCTOR	
	Limin
	5. State Oil & Gas Lease No.
T AS 31 10 3 D 3 m and T In A	State Foo X
	1-Laura Richardson-Midland 1-Foreman CRM 1-Engr. PJB 1-File SUNDRY NOTICES AND REPORTS ON WELLS 60 Serial This SUNDRY NOTICES AND REPORTS ON WELLS 60 Serial Company 35 of Operator 61 Operator 62 Serial Company 35 of Operator 63 Serial Company 35 of Operator 64 Township 75 Serial Company 15 Elevation (Show whether DF, RT, GR, etc.) Check Appropriate Box To Indicate Nature of Notice, Report or NOTICE OF INTENTION TO: 65 Serial Company 15 Elevation (Show whether DF, RT, GR, etc.) 66 Company 66 Serial Company 16 Elevation (Show whether DF, RT, GR, etc.) 66 Company 66 Serial Company 66 Company 66 Serial Company 66 Company 67 Company 68 Company 68 Company 69 Company 69 Company 69 Company 60 C

DISTRICT & SUPERCHISOR

- 11. Pressure test squeeze to 1000#. POH with workstring.
- 12. TIH and wash sand off RBP and retrieve.
- 13. GIH with bit and clean to bottom, 3706', checking for fill in the open hole section. 3397'-3706'.
- 14. POH.
- 15. Rig up Halliburton and prepare to jet wash open hole interval.
- 16. GIH with jet bit, drill collars, and workstring.
- 17. Using sand to jet, clean out open hole interval 3397'-3706'. Make several passes through interval.
- 18. Circulate hole clean with 2% KCl and then spot 900 gals. 20% acid from 3706'-3397'.
- 19. POH with bit and workstring.
- 20. GIH with workstring and 7" treating packer.
- 21. Set packer at + 3250'.
- 22. Frac open hole interval, 3397'-3706', with approximately 42,000 gals. gelled 2% KCl water, 69,000# 20/40 sand, rock salt, and benzoic flakes in 3 stages. Flush with 2% KCl.
- 23. POH with 2 7/8" tbg. and packer.
- 24. Run pump, rods, and tubing. Place well back on production.
- 25. Test well and evaluate results.

ff_B PJB/ly

