CLINE A-15 NO. 2

RE-COMPLETE IN LANGLIE MATTIX

WELL DATA

PBTD: 5770' ELEVATION: 3308' KB ZERO: 8'GL LOCATION: 660' FSL & 660' FWL, Section 15, T-23S, R-37E, Lea County, New Mexico CASING: 13-3/8", 36# surface casing @ 230' w/200 sx. 9-5/8", 36#, J-55 & H-40 production casing @ 3409' w/600 sx. TOC @ 2110' by temp. survey 7", 20#, J-55 liner from 3336' to 3874' w/200 sx. 4-1/2", 11.6#, J-55 liner from 3374' to 5800' w/230 sx.

RECOMMENDED PROCEDURE

- 1. Rig up. If necessary, load and kill well with treated fresh water.
- 2. Tag bottom with tubing and tally out of hole.
- 3. GIH w/3-7/8" bit, 4-1/2" casing scraper, and 2-3/8" tubing. Clean out liner from ±3374'-±4100'.
- 4. POOH w/bit, casing scraper and tubing.
- 5. GIH w/4-1/2" cast iron bridge plug. Set CIBP @ ±4000'. POOH w/tubing.
- 6. GIH w/9-5/8" treating packer. Set packer @ ±3100'. Pressure up on tubing to 2500 psi. (This is to determine if the top of the 7" and 4-1/2" liners will withstand the estimated treating pressure.) If the liner tops will not hold pressure, report results to the office. If the liner tops will hold pressure, POOH w/the packer, run the tubing back in the hole open ended, and proceed to step 7.
- 7. Spot 500 gals. (12 bbls.) 15% HCL-NE acid w/iron sequestering agent from 3370'-3200'. (Inhibit acid for 24 hrs. @ 100°F)
- 8. POOH w/tubing.
- 9. Rig up and run GR-Collar log from 3800'-2000'.
- 10. GIH w/3-5/8" decentralized casing gun (0.40" hole diameter and 0° phasing) w/a collar locator. Perforate from top to bottom w/1 JSPF as follows:

3240'-42', 3255', 3300', 3350', 3360', & 3370' (8 perfs. total)

11. POOH w/perforating gun. GIH w/9-5/8" treating packer and tubing. Set packer @ ±3100'.

- 12. Acidize perforations from 3240'-3370' as follows:
 - a. Pump 800 gals. (19 bbls.) 15% HCL-NE acid w/iron sequestering agent down the tubing @ 4-6 BPM.
 - b. Release 2, 7/8" ballsealers after the first 100 gals. of acid and every 100 gals. thereafter. (14 balls total)
 - c. Flush to bottom perforation (3370') w/32 bbls. treated fresh water. Limit surface treating pressure to 2500 psi.
- 13. Release packer @ 3100'. Lower packer to 3310' to knock ballsealers loose. POOH w/tubing and packer.
- GIH w/2-3/8" tubing open ended. Spot 126 gals. (3 bbls.) 15% HCL-NE acid with iron sequestering agent from 3598'-3405'. (Inhibit acid for 24 hrs. @ 100°F)
- 15. POOH w/tubing.
- 16. GIH w/3-5/8" decentralized casing gun (0.40" hole diameter and 0° phasing) w/collar locator. Perforate from top to bottom w/1 JSPF as follows:

3470'-78', 3487', 3495', 3506', 3524'-26', 3536'-56', 3574'-78', 3592'-98' (48 perfs total)

- 17. POOH w/perforating gun. GIH w/4-1/2" treating packer and 2-3/8" tubing. Set packer @ ±3400'.
- 18. Acidize perforations from 3470'-3598' as follows:
 - a. Pump 4000 gals. (95 bbls.) 15% HCL-NE acid w/iron sequestering agent down the tubing @ 4-6 BPM.
 - b. Release 2, 7/8" ballsealers after first 100 gals. acid and every 100 gals. thereafter. (78 balls total)
 - c. Flush to bottom perforation (3598') w/16 bbls. treated fresh water. Limit surface treating pressure to 4000 psi.
- 19. Release packer @ 3400'. Lower packer to 3600' to knock ballsealers loose. POOH w/tubing and packer.
- 20. GIH w/9-5/8" treating packer and 2-7/8" work string. Set packer @ \pm 3100'.
- 21. Rig up and fracture treat the Langlie Mattix perforations from 3240' to 3598' in three stages down the 2-7/8" tubing at 15 BPM as per the following:

Max. allowable surface pressure: 2500 psi. Est. wellhead treating pressure: 2500 psi.

- a. Pump 2000 gals. YF2PSD pad.
- b. Pump 2000 gals. YF2PSD w/1 ppg 20/40 sd.
- c. Pump 2000 gals. YF2PSD w/2 ppg 20/40 sd.
- d. Pump 2000 gals. YF2PSD w/3 ppg 20/40 sd.
- e. Pump 2000 gals. YF2PSD w/4 ppg 20/40 sd.
- f. Release 18, 7/8" ballsealers.
- g. Repeat steps a thru f for second stage.
- h. Repeat steps a thru e for third stage.
- i. Displace w/22 bbls. slick 2% KCL water.
- j. Record 5, 10, and 15 min. ISIP.
- k. Shut well in for 4 hrs.

FRAC FLUID COMPOSITION (DOWELL)

YF2PSD - 30,000 gals. with the following additives:

480 lbs. J84	60 lbs. J218
30 gals. F75	60 gals. J318
5200 lbs. KCL	500 gals. J221
600 lbs. J347	180 lbs. L10
60,000 lbs. 20/40 sand	

- 22. POOH w/tubing and treating packer.
- 23. Clean out fill to ±3700' w/sand pump. Run 2-3/8" production string. Swab test well and report results to the office.

PREPARED BY

<u>|10 |80</u> E DATE

SUPERVISING **ENGINEER** PRODUCTION

DIVISION ENGINEER

DATE

DRILLING SUPERINTENDENT

DATE

dlb

cc: DLW, LRS, HCP, JFB (5), CRP, MAW, FILE, DLB



MAW

NMFU

DEWILLWARTH CHI COMPANY Blow-out Ereventer Creditiontions



NCTE:

ł

API SERIES 900

Manual and Hydraulic controls with closing unit no less than 75% from well head. Remote controls on rig floor.

DUE TO SUBSTRUCTURE CLEARANCE,

HYDRILL IN NOT MUSED.