

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-27723

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

E.E. Blinebry "B"  
Federal NCT-2

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT  
Langlie Mattix Seven  
Rivers Queen

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

S26, T23S, R37E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

Unit Letter M, 660' FSL & 660' FWL

14. PERMIT NO.

30-025-10843

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3466' DF

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. MIRU.
2. TIH with workstring and circulated 10# gallon brine. Test casing to 500 psi. Casing held okay.
3. Tagged CIBP at 4900'. Spot 10 sacks (100') cement on top CIBP.
4. Pulled up and spot 20 sack plug 4000' to 4100'.
5. Pulled up and sop 60 sack plug 2850' to 3350'.
6. Perforate 5 1/2" casing at 800' with 2 shots. Circulate down 5 1/2" casing up 8 5/8" casing to top with brine water.
7. Cement with 200 sacks Class "C" cement. Circulate 10 sacks to pit.
8. Cut off wellhead. Install marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

*J.W. Browning*

TITLE

Dist. Adm. Supvr.

DATE

06/04/86

(This space for Federal or State office use)

APPROVED BY

*Sup. 301-111-111-111-111*

TITLE

DATE

9-12-86

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side