Form	3160-	5	
(Nove	mber	1994)	

Final Abandonment Notice

L. .. TED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division PPROVED 1625 N. French Dr. Exputs July 31, 1996

Hobbs, NM8982

Temporarily Abandon

Water Disposal

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Change Plans

Convert to Injection

- LCOSTAD 6. If Indian, Allottee or Tribe Name

d No

H 70

SUBMIT IN TRIPLICATE - Other instructions on reverse side			 7. If Unit or CA/Agreement, Name and/or No. Myers Langlie Mattix Unit 8. Well Name and No. 9. API Well No. 		
1. Type of Well Ø Oil Well Gas Well Other					
2. Name of Operator OXY USA WTP Limited Partnership 192463					
3a Address P.O. Box 50250 Midland, TX 79710		3b. Phone No. (include area code) 915-685-5717		30-025-108-78 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Langlie Mattix 7R-Qn-GB		
				11. County or Parish, State	
990 FSL 990 1	FEL SESE(P)	Sec 29 7235	RZZE	Lea NM	
12. CHECK AF	PROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE, R	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen C	- Production (Stat Reclamation		
Subsequent Report	Alter Casing	New Construction	Recomplete	U Well Integrity Other	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. Describe proposed or Completed Operation (clearly state an pertinent details, including estimated stating date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon

Plug Back

See Other Side

Approved as to plugging of the well bone Liability under bond is retained until surface rastoration is completed.

 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 	Title				
David Stewart	Regulatory Analyst				
Signature Vin ftt	Date 215/01				
THIS SPACE FOR FEDERA	L OR STATE OFFICE USE	······································			
Approved by (ORIG. SGD.) ALEXIS C. SWOBODA	THETROLEUM ENGINE	FEB 1 2 2001			
Conditions of approval. if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.					
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willful fraudulent statements or representations as to any matter within its jurisdiction.	ly to make to any department or agency of the Unite	d States any false. fictitious or			
(Instructions on reverse) GWW					

MLMU # 46

11/16/2000

MIRU. ND WH NU BOP. RIH w/csg scraper on tbg. Tag Solid @ 3403. POOH w/scraper. RIH w/baker Full bore pkr on 107 jts. Set pkr @ 3374. Press up to 700# for 10 min Held. Release pkr POOH SDON.

11/17/2000

Try to Press up on csg. Could Pump 2 BPM @ 200#. RIH w/ Baker Full Bore pkr & find holes from 510 to 321. POOH w/ pkr. Start to RIH open ended & well was running over. Wait on vacuum Tk. Finish RIH to 3403. Mix and pump 25 sx Class C cemt on top of CIBP. POOH w/40 jts. SD.

11/20/2000

RIH & Tag cemt plug @ 3123. Mix and spot 10 # mud from 3123 to 2765. POOH laying down tbg to 2765. Mix and pump 40sx Class C @ 2765. POOH w/tbg. RU Key Wireline and RIH w/4" perf gun shoot 4 holes @ 1270'. POOH and RDWL. RIH w/tbg and tag cemt @ 2425. POOH w/18 stds. Close in SDON.

11/21/2000

RIH w/Baker full bore pkr on ws. Set pkr @ 1133. Load BS. Est. inj rate of 1BPM @ 700 #. Pumped 20 bll thru pkr. RU POOL. Mix and pump 35 sx Class C cemt. Displace cemt. 2 blls under pkr. RD POOL WOC. Unset pkr and POOH. RIH open ended and tag top of cemt @ 1096'. POOH lay down 27 jts. RIH w/Baker cemt ret on 8 jts. Set Ret @ 255'. RU POOL. Mix and pump 125 sx. Class C cemt. To cir cemt to surface shut surf valve & squeeze 30sx. Sting. out of ret & fill up csg. POOH. SDON.