	TMEN OF THE	OF THE INTERIOR verse eide)		re- Ex			
Formerly 9-331) UEPAT TOBUE	REAU OF LAND MAN	AGEMENT					
SUNDRY N (Do not use this form for p) Use "APP	OTICES AND REF roposals to drill or to deep PLICATION FOR PERMIT	PORTS ON en or plug back "for such propo	to a different reservoir.	O. IF IN	DIAN, ALLOTTEE	OR TRIBE NAME	
1. injection well					7. UNIT AGREEMENT NAME Myers Langlie Mattix Unit		
WELL WELL OTHE	INJECTION WEL				8. FARM OR LEASE NAME		
2. NAME OF OPERATOR GETTY OIL COMPANY							
3. ADDRESS OF OPERATOR				9. WBLL			
P.O. BOX 730, HOBE	3S, N.M.	a mith any Sta	te regulrements •	10. FISI	43 10. FIELD AND POOL, OR WILDCAT		
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Ltr M 660 FSL & 660 FWL 					Langlie Mattix 11. smc., T., B., M., OR BLK. AND SUBWENT OR ARMA		
14 DEDUCT NO 15. ELEVATIONS (Show whether DF, RT, GB, etc.)					Sec. 29, T23S, R37E		
14. PERMIT NO. 15. ELEVATIONS (S		3305 GR		Lea		NM	
						<u></u>	
16. Check	(Appropriate Box To	Indicate Nati	ure of Notice, Report, c				
NOTICE OF INTENTION TO:				SEQUENT REPO	RT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING W		
FBACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT Shooting or acidizing		ALTERING CA		
SHOOT OF ACIDIZE	ABANDON® Change plans		(Other)				
(Other)	CHANGE LEANS		(Norg: Report res Completion or Rec	ults of multig	ole completion (ort and Log for	on Well m.)	
 TIH w/workstr Set RBP below Pull up and s 	IPC tbg. and AD- ing. RBP and pk leak and spot 1 set pkr. ± 75' ab at as per recomme	r. and lo O' of san ove csg. endation.	cate csg. leak. d on top of RBP.				
 9. TOH w/workstr 10. TIH w/workstr 11. Test squeeze 12. TOH w/workstr 13. TIH w/workstr 	ring and bit and to 1000#. ring and bit. ring and retrievi	ng tool.	cmt. to top of F Latch onto and F ' and return to i	POH w/wor	kstring a	ind RBP.	
 9. TOH w/workstr 10. TIH w/workstr 11. Test squeeze 12. TOH w/workstr 13. TIH w/workstr 14. TIH w/injecti 16. i hereby certify that the foreg SIGNED	cing and bit and to 1000#. ring and bit. ring and retrievi ion tbg. and pkr.	ng tool. to ±3540	Latch onto and F ' and return to i Superintendent	POH w/wor .njection		3/84	
 9. TOH w/workstr 10. TIH w/workstr 11. Test squeeze 12. TOH w/workstr 13. TIH w/workstr 14. TIH w/injecti 16. i hereby certify that the foregoing of the space for Federal or State APPROVED BY	cing and bit and to 1000#. ring and bit. ring and retrievi ion tbg. and pkr. wing is true and correct kett ate office use) . J.AMidland	ng tool. to ±3540	Latch onto and F ' and return to i Superintendent	POH w/wor .njection	атю9/28	3/84	

.

.