	P. C. Statistics
	Roman in the second of
Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	LC_054668 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	 UNIT AGREEMENT NAME FARM OR LEASE NAME
	Farnsworth 4
well gas to ther Ta'd	9. WELL NO.
2. NAME OF OPERATOR	13
Sun Exploration and Production Co.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Langlie Mattix 7 Rvrs. Q Gryb
P,O. Box 1861, Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.) AT SURFACE: Unit Ltr. ייסיי	Sec. 4, T-26-S, R-37-E
AT SURFACE: Unit Ltr. "O" AT TOP PROD. INTERVAL: 990' FSL and 1650'FEL	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Lea New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	2983.3'GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	
	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	
	change on Form 9-330.)
MULTIPLE COMPLETE	
MULTIPLE COMPLETE	
MULTIPLE COMPLETE I CHANGE ZONES I ABANDON* I (other) Pressure test	change on Form 9–330.)
MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and
MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and
MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)*
MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit)
MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit)
MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit)
MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr lay down bit and csg. scraper. RIH w/ 2 3/8" Ws, 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg aper, Tag up at 3236. POH and RDG pkr and RBP.
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr lay down bit and csg. scraper. RIH w/ 2 3/8" Ws, Set RBP at 3190'. Set pkr at 3127' and test RBP 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg raper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and
MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg raper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and ire up.
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr lay down bit and csg. scraper. RIH w/ 2 3/8" Ws, Set RBP at 3190'. Set pkr at 3127' and test RBP annulus w/ inhibited prod. wtr. unable to pressu 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg caper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and the up. e in 5 1/2" csg approx. 18' belo
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr lay down bit and csg. scraper. RIH w/ 2 3/8" Ws, Set RBP at 3190'. Set pkr at 3127' and test RBP annulus w/ inhibited prod. wtr. unable to pressu Wtr flow around wellhead. Dug out and found hol tbg. flange. Using RDG pkr tested csg at 500 PSI Tested O.K. POH and lay down Pkr. RIH w/ 2 3/8" 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg aper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and ire up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'.
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr lay down bit and csg. scraper. RIH w/ 2 3/8" Ws, Set RBP at 3190'. Set pkr at 3127' and test RBP annulus w/ inhibited prod. wtr. unable to pressu Wtr flow around wellhead. Dug out and found hol tbg. flange. Using RDG pkr tested csg at 500 PSI Tested O.K. POH and lay down Pkr. RIH w/ 2 3/8" 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg aper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and ire up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'.
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr lay down bit and csg. scraper. RIH w/ 2 3/8" Ws, Set RBP at 3190'. Set pkr at 3127' and test RBP annulus w/ inhibited prod. wtr. unable to pressu Wtr flow around wellhead. Dug out and found hol tbg. flange. Using RDG pkr tested csg at 500 PSI Tested O.K. POH and lay down Pkr. RIH w/ 2 3/8" 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg aper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and ure up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'. WS and retrieving head. Retriev
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr lay down bit and csg. scraper. RIH w/ 2 3/8" Ws, Set RBP at 3190'. Set pkr at 3127' and test RBP annulus w/ inhibited prod. wtr. unable to pressu Wtr flow around wellhead. Dug out and found hol tbg. flange. Using RDG pkr tested csg at 500 PSI Tested O.K. POH and lay down Pkr. RIH wf 2 3/8" Subsurface Safety Valve: Manu. and Type 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg aper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and ure up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'. WS and retrieving head. Retriev
 MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg aper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and tre up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'. WS and retrieving head. Retriev Set @ Ft
 MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Pressure test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 3-28-83 MIRU pulling unit (location broke through had to POH w/rods. Install BOP. POH and laydown tbg. RI scraper and 40 jts 2 3/8" Ws. SDFN. 3-29-83 Finish RIH w/ 2 3/8" Ws, 4 3/4" bit and csg. scr lay down bit and csg. scraper. RIH w/ 2 3/8" Ws, Set RBP at 3190'. Set pkr at 3127' and test RBP annulus w/ inhibited prod. wtr. unable to pressu Wtr flow around wellhead. Dug out and found hol tbg. flange. Using RDG pkr tested csg at 500 PSI Tested O.K. POH and lay down Pkr. RIH wf 2 3/8" Subsurface Safety Valve: Manu. and Type 	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg aper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and tre up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'. WS and retrieving head. Retriev Set @ Ft
 MULTIPLE COMPLETE	change on Form 9-330.) e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* o use tandemtruck to spot unit) H w/ 4 3/4" bit, csg aper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and ire up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'. WS and retrieving head. Retrieving Set @Ft
MULTIPLE COMPLETE	e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* • use tandemtruck to spot unit) H w/ 4 3/4" bit, csg raper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and ure up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'. WS and retrieving head. Retriev
MULTIPLE COMPLETE	e all pertinent details, and give pertinent dates irectionally drilled, give subsurface locations and it to this work.)* • use tandemtruck to spot unit) H w/ 4 3/4" bit, csg raper, Tag up at 3236. POH and RDG pkr and RBP. to 500 PSIG. Release Pkr and ure up. e in 5 1/2" csg approx. 18' belo G from RBP at 3190' to 60'. WS and retrieving head. Retriev

- Cartan

.

-

*See Instructions on Reverse Side

ROSWELL, NEW MEXICO

RECEIVED •. t t O.C.D. HOBBS OFFICE 5 5

1983

Farnsworth 4 #13

3-30-83 Remove BOP, Install Wellhead RR 8:00 AM

-

. .: •

•

RECEIVED

AUG 24 1983

O.C.D. NOB85 OFFICE

s,