

1. Rig. Up. Pull rods and pump. Install BOP. Pull tubing.
2. Clean out to 3300'.
3. Acidize Open-Hole section 3139'-3300' W/ 3000 gal Mud acid in 3 stages using 500# rock salt between stages. Flush W/2% KCL Water.
4. Frac Open-Hole W/18,000 Gals CO2 and 18,000 Gals X-linked Gelled 2% KCL water containing 6000# 100 mesh sand, 36,000# 20/40 sand and 24,000# 10/20 sand. Flush W/500 Gals CO2 and 500 Gals X-Linked gelled 2% KCL Water.
5. Set RBP @ 3130'.
6. Perforate 5 1/2" csg W/2-JSPF from 3103' - 3111' and from 3115' - 3120'.
7. Set packer @ 3050'. Acidize perforations 3103' - 3120' W/1000 Gals Mud acid and 60 Ball sealers.
8. Frac perfs. 3103' - 3120' W/ 15,000 Gals X-Linked gelled 2% KCL Water and 15,000 Gals CO2 containing 28,000# 20/40 sand and 30,000# 10/20 sand. Flush W/500 Gals CO2 and 500 Gals X-Linked Gelled 2% KCL Water.
9. Pull RBP and Packer
10. Run Production Equipment. Test and return to production.3