

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

3a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator American Exploration Company		8. Farm or Lease Name E. C. Hill "C"
3. Address of Operator 2100 RepublicBank Center, Houston, Texas 77002		9. Well No. 1
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE. SECTION 27 TOWNSHIP 23S RANGE 37E N.M.P.M.		10. Field and Pool, or Wildcat Teague Blinbery
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

American Exploration Company proposes to perforate and acidize the subject well as follows:

RU WSU. Pull prod. equip. ND wellhead. NU BOP. Tag PBTD. Strap out of hole. RIH w/bit, collars and tbq. Drill out or push junk @ +/-5902' to bottom (+/-6366. POH. Perforate using a 4" steel hollow carrier casing gun w/2 premium 5347-52', 5339-43', 5320-28'. RIH w/RBP and pkr. Set plug @ 5510'. Set pkr. @ 5190'. Acidize w/4000 gals. 15% NEFE containing surfactant and inhibitor + 400# moth balls in 5 equal stages. Adjust divert as necessary after Stage 1. Overflush w/20 bbl. 2% KCL water. Pump @ 5-7 BPM. RU swab. Swab back load. Retrieve plug and POH. RIH w/oroduction tbq. ND BOP. NU wellhead. RIH w/production equipment. Hang well on.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Marty McClanahan TITLE Production Dept. DATE October 12, 1988

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: