

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

McCallister B-1 well file
SUBMIT IN TRIP
(Other instructions on reverse side)

Form approved
Budget Bureau No. 1004-013
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Earl R. Bruno 915/685-0113	8. FARM OR LEASE NAME McCallister "B"
3. ADDRESS OF OPERATOR P. O. Box 590, Midland, Texas 79702	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below) At surface 2310 ft. FSL and 330 ft. FEL Unit I	10. FIELD AND POOL OR WILDCAT Scharborough-Yates 7 Rivers
14. PERMIT NO.	11. SEC., T., R., M., OR B.L.K. AND SURVEY OR AREA 25-26S-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 2939 DF	12. COUNTY OR PARISH Lea
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETION	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

WORK COMPLETED:

1. 5 1/2" CIBP preset at 819 ft.
2. RHH with Bailer and chase CIBP to 3120 ft.
3. RHH with second CIBP and set at 3100 ft.
4. Load hole with brine and saltwater gel.
5. Pump 10 sacks on top of CIBP.
6. Cut and pull 2504 ft. 5 1/2" casing.
7. Load hole with brine and saltwater gel.
8. Pump 35 sacks at 2547 ft. and WOC.
9. RHH and tag plug at 2490 ft.
10. Pump 20 sack plug at 2490 ft.
11. Pump 35 sack plug at 1200 ft.
12. Pump 35 sack plug at 559 ft. and WOC.
13. Tag plug at 451 ft.
14. Set 10 sack surface plug.
15. Set hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Jay Morris TITLE Agent DATE 11/16/89

(This space for Federal or State office use)

Orig. Signed on 11/16/89

APPROVED BY _____ TITLE _____ DATE 11/30/89

CONDITIONS OF APPROVAL, IF ANY:

Approved by _____
L. McCallister
surface and subsurface

*See Instructions on Reverse Side