

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
LC-030176

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☐ GAS WELL ☒ OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
MERIDIAN OIL INC.

8. FARM OR LEASE NAME
RHODES GSU

3. ADDRESS OF OPERATOR
P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.
915-688-6906

9. WELL NO.
12

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
P, 660' FSL & 660' FEL

10. FIELD AND POOL, OR WILDCAT
RHODES YATES

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

9, T-26-S, R-37-E

14. PERMIT NO.
30-025-24534

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
2989.7' GR

12. COUNTY OR PARISH
LEA

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other)

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other)

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MOVED IN ON WELL AND INITIATED TA OPERATIONS, WHILE WORK IN PROGRESS, DECIDED TO PLUG AND ABANDON WELL. CALLED THE BLM AND TALKED TO MR. JIM AMOS AND OBTAINED VERBAL APPROVAL TO ABANDON.

PLUG AND ABANDON PROCEDURE

1. Notify Andy Cortez with BLM in Hobbs. Set CIBP at 2800'. Cap CIBP with 75' of cement (5 sxs). Pull up above plug and circulate hole with 9 ppg gelled brine, POOH. Perforate four squeeze holes at 2640'. Establish pump-in rate down casing.
2. If no rate can be established then RIH open ended and set a 130' cement plug (10 sxs) across the base of the salt at 2510'-2640'. If a pump-in rate is established, then set a cement retainer at 2510'. Squeeze under retainer with 35 sxs of cement. Pull out of retainer and cap it with 5 sxs. POOH.

CONTINUED ON PAGE -2-

18. I hereby certify that the foregoing is true and correct

SIGNED Maria L. Perry

TITLE PRODUCTION ASST.

DATE 5-8-92

(This space for Federal or State office use)

APPROVED BY David P. Glass

CONDITIONS OF APPROVAL, IF ANY:

DATE 5-15-92

*See Instructions on Reverse Side

3. Perforate four squeeze holes at 1340'. Establish pump-in rate down casing with braidenhead open and attempt to establish circulation. If circulation is established, then pump 400 sxs cement down casing and allow to circulate out braidenhead. If circulation is not established during pump-in test, then continue with step No. 4&5.
4. Do step 4 & 5 if circulation was not established. Set retainer at 1220' and squeeze under retainer with 35 sxs of cement. Pull out of retainer and spot 5 sxs on retainer, POOH. Perforate four squeeze holes at 690'. Establish pump-in rate from surface and test for circulation out of braidenhead.
5. Pump 200 sxs from surface allowing circulation out braidenhead. Do not displace.
6. Lay down workstring, RDMO PU. Cut off casing 3' below ground level, install P&A marker, and reclaim location.