SUNDRY NO	AU DE LAND MANAGEME TICES AND REPORTS	ON WELLS	6. т	NM-795 F INDIAN, ALLOTTER	
(Do not use this form for propulse "APPLIC	orals to drill or to deepen or plu ATION FOR PERMIT—" for suc	ng back to a different reservoir. h proposals.)	7 0	NIT AGREEMENT NA	V P
OIL GAS OTHER	convert to WIW		" "	MIL ROBERS NEW YEAR	4. A
. NAME OF OPERATOR			- 1	eonard Bros.	
Talkee off conpany				WELL NO.	
7990 IH 10 West, San				4	
See also space 17 delow.)			Ì	O. FIELD AND POOL, OR WILDCAT	
			I	S. Leonard 11. sec., t., R., M., or blu. and survey or area	
3. PERMIT NO.	15. ELEVATIONS (Show whether	OF BT. GR. etc.)		C. 13, T26S	
	3003 KB, 2993 GL	, , ,		Lea	New Mexico
6 Check A	· · · · · · · · · · · · · · · · · · ·	Nature of Notice, Report, o	r Other	Data	
NOTICE OF INTE				BFOAT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRING W	ELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT		ALTERING CA	
SHOOT GR ACIDIZE	ABANDON* CHANGE PLANE	SHOOTING OR ACIDIZING (Other)CON	vert t	ABANDONMEN WIW	T*
(-ither)		(Nors: Report resi	ults of mu	ultiple completion of Report and Log for	
7. DESCRIBE PROPOSED OF COMPLETED OF proposed work. If well is direct	ERATIONS (Clearly state all pertionally drilled, give subsurface b	nent details, and give pertinent da	tes, includ	ling estimated date	of starting any
nent to this work.) • 1. MIRU PU.		ocacions and measured that true ver	rtical depi	ins for all markers	and somes perti-
1. MIRU PU. 2. Pull rods and pump 3. NUBOP. Tag bottom 4. RIH w/ 2 7/8" tubin xylene/15% HCL. Fi 5. Unset pkr. POOH w/ 6. RIH w/plastic coate w/ 2% KCL containin 7. Set PKR at 3300' 8. Hook up injection 19. RDPU.	and pull tubing. Ing and treating packlush tubing w/2% KCI pkr and tbg. ed tbg and plastic ong corrosion inhibit NDBOP. Line.	ker set PKR at 3350'.	Trea packer	t perforation	ons with
1. MIRU PU. 2. Pull rods and pump 3. NUBOP. Tag bottom 4. RIH w/ 2 7/8" tubin xylene/15% HCL. Fi 5. Unset pkr. POOH w/ 6. RIH w/plastic coate w/ 2% KCL containin 7. Set PKR at 3300' 8. Hook up injection in RDPU.	and pull tubing. Ing and treating packlush tubing w/2% KCI Pokr and tbg. Ed tbg and plastic of corrosion inhibit NDBOP. Line. Is true and correct	er set PKR at 3350'. coated Guiberson uni-poor, oxygen savenger a	Treapacker	t perforation I. Circula ocide.	ons with
1. MIRU PU. 2. Pull rods and pump 3. NUBOP. Tag bottom 4. RIH w/ 2 7/8" tubin xylene/15% HCL. Fi 5. Unset pkr. POOH w, 6. RIH w/plastic coate w/ 2% KCL containin 7. Set PKR at 3300'. 8. Hook up injection 19. RDPU. 8. I hereby certify that the regoing SIGNED	and pull tubing. Ing and treating packlush tubing w/2% KCI Pokr and tbg. Ed tbg and plastic of corrosion inhibit NDBOP. Line. Is true and correct	er set PKR at 3350'. coated Guiberson uni-partor, oxygen savenger a	Treapacker and bi	t perforation I. Circula ocide.	ons with