

W. H. RHODES 'B' NCT-2

WELL NO. 4

1. Rig up. Pull rods and pump. Install BOP. Pull tubing.
2. Set packer @ 3250'. Acidize perfs. 3289' - 3318' W/2000 Gals. MSR acid and 25 ball Sealers.
3. Perforate 5 1/2" casing W/ 1-JSPF @ 3122', 23', 32', 37', 39', 44', 59', 69', 71', 74', 76', 80', 84', 90', 95', 98', 3201', 03', 11', 18', 25', 31', 35', 37', 41', 53', 59', and 3265'.
4. Set RBP @ 3280' and spot 5' sand on top of plug. Set packer @ 3080'.
5. Acidize perfs. 3122' - 3265' W/ 3000 Gals. MSR acid and 60 ball sealers.
6. Frac 5 1/2" casing perfs. 3122' - 3265' W/25,000 gals. X-linked gelled water and 25,000 gals. CO2 W/53,000# 20/40 sand and 52,000# 10/20 sand in 2 stages using 300# rock salt between stages. Flush with gelled water and CO2.
7. Clean out and pull RBP.
8. Reset RBP @ 3090' and spot 5' sand on top of plug.
9. Perforate 5 1/2" casing W 1-JSPF @ 3021', 25', 36', 41', 46', 57', 60', 63', and 3068'.
10. Set packer @ 2960'. Acidize perfs. 3021' - 3068' W/2000 Gals MSR acid and 25 Ball Sealers.
11. Frac 5 1/2" casing perfs. 3021' - 3068' W/16,000 Gals X-linked gelled water and 16,000 gals. CO2 using 35,000 lbs. 20/40 sand and 30,000 10/20 sand. Flush W/gelled water and CO2.
12. Pull packer and RBP.
13. Install Production equipment. Test and place on production.