ATTACHEMENT A

- Tubing pressure 2000, blow down in 30 minutes, swab well down to 13,200, closed in for night.
- Tubing pressure 1950, blow down in 50 minutes. 5/30/79

J,

- Tubing pressure 1300, release packer, pull out, rig up Welex wire line bridge plug, set at 14,030, pull our of hole, smat down.
- 6/15/79 Welex dumped 35' cement on plug. Plug back TD 13,995', rig up & perforate as follows: 12,490-92, 12,494-93, 12,500-502, 12509-511, 12,517-28, 12,536-38, 12,554-56, 12,560-65, all perforations 1 shot per ft., total 35' 05 holes, made up 4 1/2 Baker Lock Sev Proker, run in hole, close well in.
- Halliburton spotted 500 galkons 15% NE Acid at 12,582, set packer at 12,424, pump held away, swabbed dry wit: small flare gas ahead of swab, close well in.
- 6/17/79 Tubing pressure 250 lbs., gas would falre for approximately 30 minutes, well died, closed in.
- Tubing pressure 200, blowed down, rig up Halliburton, treat with 8000 gallons 6/13/79 Mod-202 acid, started swabbing, swabbed to 9500', had some oil and some gas, close well in.
- Subing pressure 700, blowed off real quick. +/19/79
- 6/20/79 Tubing pressure 600, blowed off in 20 minutes, fluid level 9000', swab to 11,500, swab well until noon and close in.
- 7/21/79 Tubing pressure 300, fluid level 8,000', run to 11.500', little oil and some gas, released packer, pulled out of hole, closed well in.
- 6/22/79 Made up redressed packer, Baker Lock Set, run in hole, set at 13,467', rig up Welex, run tubing gun, perforate as follows: 13,529-31, 13,535-39, 13,580-82, I shots per ft., started swabbing, swab to 10,000', small show of gas, close well in.
- Tubing pressure 500, blow down in 15 minutes, swab to 11,500', close well in. 10/23/79 711/79 lubing pressure 1100, blowed down in 20 minutes, swabbed dry, slight gas flare, rig up Halliburion to treat, treat with 1500 gallons MOD-202 20%, blowed down in 15 minutes, started swabbing, swabbed well down to 8000', close well in.
- 7/46/79 Tubing pressure 1000, flowed for 15 minutes, swabbed well dry, closed in at 2: YO PM
- + //////) Tubing pressure 1100, bleed down to 250 lbs. in 10 minutes, blowed for 1 hr. %30 minutes, died down to approximately 100 MCF, rig up Welex to perforate with tibing gue, perforate as follows: 13,955-56 2 roles, 13,959-61 3 holes, at 17,904 - hole, 13,967-69 3 holes, 13,973-74 2 holes, 11 holes total, spotted 700 gallone of Halliburton MSA acid, reset packer at 13,815, Halliburton pressured up on tubing, average rate 1 bbl. per minute at 4500 lbs., start gwabbing, gwabbed to 11,500, close well in.
- Thing pressure 500, blowed down in 20 minutes, close well in.
- 19/79 Publing pressure 600, blowed down in 20 minutes, swabbed to 12,000, blowed down, of an well in.
- $^{+}$ / $^{\prime\prime}$) libits pressure 1440, blowed for 1 1/2 hrs., run swab to 11,500, very little fluid, close well in, release pulling unit.
- 1/ +770 Tubing pressure 500 lbs., fluid level 12,000' from surface, install BOP, unseat packer, set packer at 13,468, swab to 8000!.
- 7. 779 Tubing pressure 1525, flowed for 1 hr. and 30 minutes, swab down to 13,000, gas blow was strong after each run, close well in, hook up recorder, release pulling machine.

- 77.3/79 Tubing pressure 4000, casing pressure 1050, well closed in for 66 hours, small blow, close well in after 2 1/2 hrs.
- Shut in time 72 hrs., tubing pressure 4400, 1:45 tubing pressure 100, close well in. Estimated volume 3/8" orfice, 61 MCF, heading from 0 to 28".

 Open at 11:30 AM tubing pressure 7200, flowed tubing 2 hrs. and 45 minutes, tubing pressure 20 psi, closed in.