STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT	·	
OIL CONSERVA	TION DIVIGION	
P. O. BO.	< 2030	
SANTA FE, NEW	MEXICO 87501 Fam C-103 - Revised 19-1-7	
U.3.G.3.	Su, Indicate Type of Louis	
DECTATION I	Sinie X Feo	
	5. State Off & Gus Leann No. L-4785	
SUNDRY NOTICES AND REPORTS ON	WELLS	
OIL CAS X WELL OTHER.	7. Util Agreement Heave	
Amoco Production Company	d. Farm or Leave hume	
J. Aduress of Operator	State IT	
P. O. Box 68, Hobbs, New Mexico 88240	9i No. 1	
VEIT LETTER F 1980 VEET FROM THE North		
THE West LINC. SECTION 16 TOWNSHIP 26-S	33-Е	
Hill Hill Hill Hill Hill 15. Elevation (Show whether L		
32.6' R		
Check Appropriate Box To Indicate No.	ture of Notice, Report or Other Data	
	SUBSEQUENT REPORT OF:	
TEMPOBARILY ABANDOR	REMEDIAL WORK	
PULL OR ALTER CASING	COMMENCE DRILLING OPNS. PLUG AND ABANCONMENT	
Отнее	ОТНЕЯ	
Work) SEE RULE 1103. Moved in service unit 5-23-83. Bled well down		
Moved in service unit 5-23-83. Bled well down	S, and give pertinent dates, including estimated date of starting any proposed	
Moved in service unit 5-23-83. Bled well down. Remove tree and installed blow out preventer. Circulated hole and checked for flow and OK. 5' of tubing collapsed. Ran shoe, bushing, and tubing. Circulated and clean out bottom to 9595'. Taggood fick to 05000		
Collapsed tubing Ran tubing target to a solution agged (150 to 9563) and recovered 4' of		
lag at 95/3' and mill to 95/6' Milling of the million of the milli		
9583 -9592'. Latched on to fich at or only it hours at 9570 to 9581 a million fish from		
Cutter and cut tubing at 106261 con a since on a sea Jank to 11945 . Rail Treepoint and chemical		
Recovered 18' 2-7/8" tubing 32' of 2 7/0" here condition mud. Fulled cubing and overshot.		
spud bars, chemical cutters and cut tubing at 114	. Unable to release packer. Ran freepoint	
rope socket. Pulled up 31 standard and	- , hung up culler at 1760, and pulled out of	
Jars, arill collars and tubing latel	recover tish. Ran overshot	
2-7/8". Ran shoe and 12' extension. Tagged at 1 pump & washed from 11503'-11595'. Tagged top of	1424'. Reverse unit broke down Repaired	
puried up off of fish Polosedd nostra off of	11424 · Latter onto fish at 11424' and	
to circulate. Perf at 00161 parts in the second	IUDING DIUGGED and Unable	
and no yain. Loss on flang Day but the	The service of the se	
Ran tubing and tagged at 14135'. Cleaned out to 0+4-NMO(2011 1-HOU R. E. Ogden RM 21.150 1-F. d.	4582' Flared for 45 min. Pumped 10 hbls 104	
1-Pétre Travis the internation move is true and complete to the best of m	Nash, HOU RM 4.206 1-SUSP 1-PJS	
	. Admin. Analyst 8-4-83	
ORIGINAL SIGNED BY JERRY SEXTON	DATE	
DISTRICT SUPERVISOR	A110 0 1000	
ONDITIONS OF APPROVAL, IF ANVI	<u>AUG 8 1983</u>	

brine. Rigge dup Dresser Atl 5-9-83 and ran gauge ring. Unc 2 to get passed 7300'. Pulled out of hole. Ran gauge ring, junk basket and sinker bars. Worked to 7645'. Pulled out of hole and ran tubing, profile nipple, packer and on-off tool. Test to 9000 PSI. Set packer at 11276'. Removed blow out preventer and install tree. Perforated 14312'-16', 14322'-34', 14340'-46', 1435 74' and 14378'-90', Opened choke and bled. Flowed 100 BLW in 3 hrs. with 10'-12' flare. Flowec well 7-1/2 hours and recovered 56 BLW and 9 BW. Flared 15'. Shut in 13-1/2 hrs. Moved out service unit 6-12-83. Shut in 24 hours and reconnected to pipeline. Repaired wellhead valves and ring gaskets. Began flow testing and flowed 21 BC, 15 BW and 1943 MCF in 144 hours. Last 24 hours flowed 2 BC, 2 BW and 340 MCF. Returned to production.

5-O.C.D. HOBBS OFFICE

STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT	
DIL CONSERVATION DIVISION P. O. BOX 2088	
SANTA FE, NEW MEXICO 87501	Form C-103 - Revised 19-1-7
U.3.G.3.	
	Su, Indicate Type of Leuse State X Fee
OZENA DA	S. State Oli & Gus Leana No.
SUNDRY NOTICES AND REPORTS ON WELLS	L-4785
100 NOT USE THIS PORT THE TOPOLOGICAL OF DELLA ON CHEN CA PUR ALL ON WELLS USE "APPLICATION TO FERMIT -" FORT C. LOIL FOR SUCH PHOPOSALC.]	AHHHHHHA -
OIL GAS WELL OTHER.	7. Unit Agreement Manie
2. Name of Operator	8. Farm or Lease liame
Amoco Production Company	State IT
P. O. Box 68, Hobbs, New Mexico 88240	91 No. 1
UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980	10. Field and Pool, or Stideat Und. Atoka
THE West LINE SECTION 16 TOWNSHIP 26-S NANCE 33-E	
Nur	
3292.6 RDB	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or C NOTICE OF INTENTION TO:	
NOTICE OF INTENTION TO: SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK X	
TEMPORARILY ABANDON	ALTERING CASING
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANCONMENT
OTHER	<b>F</b>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includir work) SEE RULE 1103.	ng estimated date of starting and
Propose to repair tubing to eliminate casing pressure and open additio	e, contrag any proposes
Kill woll with 17 Flue 1 - the second second open address	nal pay as follows:
Kill well with 17.5#/Gal mud by circulating around collapsed tubing a come off on-off tool and pull out of hole. If successful proceed with	t 9555'. Attempt to
tubing is already parted on parts present in successful proceed wit	n next two steps. If
<ol> <li>Run in hole with workstring and 2-7/8" N-80 tubing. Set packer a 14.64#/gal mud.</li> </ol>	
14.64#/gal mud.	c 11,013 and circulate
<ol> <li>Latch onto on-off tool and release packer and pull out of hole.</li> <li>If tubing is parted or parts pull out of hole with freepipe.</li> </ol>	
Run in hole and latch onto fish. Release packer and pull out of hole. with $4.00"$ seal bore on wireline and set at $11.600'$ inside $7-5.60"$ and	Dum in 1 1
with 4.00" seal bore on wireline and set at 11,600' inside 7-5/8", 39#	Kun in hole with packer
hole with tubing and tailpipe as follows: 1) Run $2550'$ $2-3/8"$ $4.6#$ Van tubing as tailai	io casing. Run in
bottom. Tailpipe should land at 141501+	ile nipple 1 joint off
2) Run seal assembly for 4,00" packer and latch into name	
	•
0+4- NMD(D) H 1 1011 1 Find to surface.	
A A A A A A A A A A A A A A A A A A A	
Tista (	
and Jump Jema Assist. Admin. Analyst	
	DATE 5-19-83
ORIGINAL SIGNED BY JERRY SEXTON	
ONDITIONS OF APPROVAL, IF ANY	- DATE MAY 19 1983
	e

e i stand

5) Install blanking plug in 1.875" profile nipple. Come off on-off tool and circulate mud out of hole with 10# brine. Latch onto on-off tool and pull blanking plug. Rig up PERF Company. Run thru tubing guns and perforate Atoka intervals 14,378'-14390'-14352'-14374', 14340'-14346', 14322'-14334', 14312'-14316'. Swab, flow back well and put on production.

MAY 19 1983 MOBBS C.D. OFFICE