

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Enron Oil & Gas Company		8. Farm or Lease Name Moore 34 Com.
3. Address of Operator P. O. Box 2267, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>north</u> LINE AND <u>1980</u> FEET FROM THE <u>east</u> LINE, SECTION <u>34</u> TOWNSHIP <u>24S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Pitchfork Ranch (Wlfcp)
15. Elevation (Show whether DF, RT, GR, etc.) 3401.6' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Existing wolfcamp perfs 13,490 to 13,500 feet.

1. Circulate the hole with 9.8#/gal mud. Spot 35 sacks C1 H cmt from 13,210 to 12,900 feet.
2. Spot 25 sacks from 12,350 to 12,150 (top of wolfcamp 12,249).
3. Spot 2t sacks from 9350 to 9150 (top of Bone Spring)
4. Cut and pull 5-1/2" casing; top of cement estimated at 7000 feet.
5. Spot 35 sacks across cut.
6. Spot 35 sacks across 8-5/8" casing shoe at 5260'.
7. Spot 35 sacks from 650 to 550 feet.
8. Spot 20 sacks at surface.
9. Weld on dry-hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Betty Gildon Betty Gildon TITLE Regulatory Analyst DATE 6/18/87

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 11/22/1987

CONDITIONS OF APPROVAL, IF ANY: