

5. SET CIBP @ 3275' AND CAP W35' CEMENT (PBTD 3240').
6. PERFORATE 5 1/2" CSG W/2-JSPF FROM 3127-3154'; 3161-3164'; 3190-3208'; & 3214-3224'.
7. ACIDIZE PERFS 3127-3224' W/6000 GALS 15% NE ACID AND 80 BALL SEALERS.
8. PULL PKR AND RBP. INSTALL PUMPING EQUIPMENT.
9. PULL PUMPING EQUIPMENT. SET PKR @ 3048'.
10. FRAC PERFS 3127-3224' W/24,000 GALS X-LINKED GEL 2% KCL ACID WATER, 21,500 GALS CO2, 60,000# 20/40 SAND & 3000# ROCK SALT IN 3-STAGES.
11. INSTALL PUMPING EQUIPMENT. ON 24 HOUR POTENTIAL TEST ENDING 11-7-84, WELL PUMPED 19 BO & 3 BW.