

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30236
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9312
7. Lease Name or Unit Agreement Name West Dollarhide Queen Sand Unit
8. Well No. 115
9. Pool name or Wildcat Dollarhide Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3124' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Sirgo Operating, Inc.
3. Address of Operator P.O. Box 3531, Midland, Texas 79702	4. Well Location Unit Letter E : 1400 Feet From The North Line and 1210 Feet From The West Line Section 5 Township 25S Range 38E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-25-90 MI&RU PU. RU cable spooler. POH w/tbg, cable, sub-pmp & motor. RIH w/5-1/2" treating pkr & 2-7/8" tbg. Leave pkr swinging. Flange up & SION.

2-26-90 Pump 1000 gal 15% HCL NEFE acid to pickle tbg. Reverse out acid. Set pkr. Load & test csg to 500# for 30 min - okay. Acidize zone w/1300 gal SWIC acid, blocking w/400# rocksalt in 4 bbls brine gel. Swab back load. POH w/tbg & pkr. RIH w/motor, sub-pump, cable & tbg. Set 5N@3455' + tbg @ 3453' Hang well on & start pumping.

2-27/3-2-90 Testing

3-3-90 TEST: 60 BO 1272 BW .3 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Atwater TITLE Production Technician DATE 4-10-90

TYPE OR PRINT NAME Bonnie Atwater TELEPHONE NO. 915/685-0878

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE APR 13 1990

CONDITIONS OF APPROVAL, IF ANY: