Submit 3 Copies to Aj propriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

CONDITIONS OF APPROVAL, IF ANY:

Form C	-103
Revised	144


DISTRICT I P.O. Box 1900, Hobbs, NM SEAU P.O. Box 200 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PER (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OR. WELL X GAS WELL OTHER	87504-2088 LS OR PLUG BACK TO A	WELL API NO, 30 025 31538 5. Indicate Type of Lease STATE FEE X 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name RR Sims "A"		
2. Name of Operator		8. Well No.		
Texaco Exploration and Production Inc.		2		
3. Address of Operator		9. Pool name or Wildcat		
P. O. Box 730 Hobbs, NM 88240		NW Teague Devonian		
Unit Letter N : 660 Feet From The S	Line and	1650 Feet From The W Line		
Section 4 Township 23S Ran		NMPM Lea		
10. Elevation (Show whether I				
GR=3320', KB=3337				
11. Check Appropriate Box to Indicate N	lature of Notice, Re	port, or Other Data		
NOTICE OF INTENTION TO:	SUB	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK			
		L. ALTERING CASING L.		
	COMMENCE DRILLING	OPNS. L PLUG AND ABANDONMENT .		
PULL OR ALTER CASING	CASING TEST AND CE	MENT JOB 🗌		
OTHER: Perf add'l Devonian, acidize	OTHER:	П		
12 Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Set 5 1/2" CIBP @ 7550', cap w/5' cement. 2) Perf w/2 JSPI @ 7466-71, 7477-81, 7485-97 (42 holes). 3) Acidize new perfs w/1500 gal 20% NEFE. 4) Evaluate new interval.				
I hereby certify that the information above is true and complete to the best of my knowledge and be	slief.			
CAN OR	Many Assa	10 10 00		
MONATURE	Liigi Asst	DATE 10-12-93		
TYPEOR PRINT NAME L.W. Johnson		TELEPHONE NO.505-393-7191		
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR TITLE		OCT 12 1993		
	-	TA TTD		

_ mle .

__ DATE _

· 47 1 % 1993

OOD HOOSE



R. R. Sims 'A' No. 2 <u>Workover Procedure</u>

- 1. MIRU pulling unit. Install BOP. Release packer and retrieve RBP. Kill well w/ clean 9.3 ppg brine cut water. TOH. Lay down UNI-V packer and RPB.
- RIH w/ 5 1/2" CIBP on wireline and set at 7550' and cap w/ 5 feet cement.
- Perforate the Devonian formation in the following intervals with a 3 1/8" casing gun, 120 degree phasing w/ 2 JSPF:

7466' - 7471', 7477' - 7481', 7485' - 7497'

Total of 21 perforated feet, 42 holes.

- 4. TIH w/ 5 1/2" Guiberson UNI-VI packer on 2 7/8" tubing to 7502'. Load hole with 2% KCL water. Spot 2 barrels acid across perforations if well is balanced. Pull packer up to 7450'. Reverse out any acid that may be in the annulus. Establish injection rate and acidize Devonian perforations as follows:
 - A. Drop 15 1.3 SG ball sealers to set in pre-existing perfs.
 - B. Pump 500 gallons 20% NEFE acid.
 - C. Drop 30 1.3 SG ball sealers.
 - D. Pump 500 gallons 20% NEFE acid.
 - F. Drop 30 1.3 SG ball sealers.
 - G. Pump 500 gallons 20% NEFE acid.
 - H. Displace to top perf with 2% KCL Water.

Note: anticipated rate of 2-3 BPM at a max surface pressure of 2100 psi.

- 5. Swab and flow well and evaluate for artificial lift equipment.
- 6. Rig down and move off location.

ACID ADDITIVES PER 1000 GALLONS

- 1 gallon surfactant
- 5 gallons acetic acid
- 2 gallons inhibitor
- 10 gallons citric acid
- 10 gallons Fe++ control

E. ED

007 1 ≠ 19**93**

Nib mudds appidt