	· ~	<i>~</i> .0.	OIL CONS. COMMISSION BOX 1980 BS. NEW MEXICO 88240
Form 3160-5 (June 1990)	DEPARTME	NT OF THE INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF LAND MANAGEMENT		5. Lease Designation and Serial No. LC 064118
<b>D</b>	SUNDRY NOTICES	6. If Indian, Allottee or Tribe Name	
	Use this form for proposals to d Use "APPLICATION FC	drill or to deepen or reentry to a different reservoir. DR PERMIT—" for such proposals	
	SUBMI	7. If Unit or CA, Agreement Designation	
1. Type of W TY Oil Well	Gas Other	8. Well Name and No.	
2. Name of (	Operator	E. C. Hill 'B' Federal #1	
	S PETROLEUM OPERATING CO	9. API Weil No.	
	nd Telephone No.	30-025-32586	
415 WEST WALL, SUITE 1000, MIDLAND, TEXAS 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area
1125' FSL & 520' FWL			Teague Devonian
Sec 3	5, T23S, R37E, Unit M		11. County or Parish, State
			Lea Co., NM
12.	CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent		Change of Plans
			New Construction
LJ Subsequent Report			Non-Routine Fracturing
Final Abandonment Notice		Casing Repair	Water Shut-Off
		Other	Conversion to Injection Dispose Water
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give s 11-07-94	RU WLT. PU 4" csg gun 60'-61'-62'-63'. RD WI Reverse 130 bbls KCL t	all pertinent details, and give pertinent dates, including estimated date of startin, ical depths for all markers and zones pertinent to this work.)* 1, TIH perf: 2 SPF 24 holes 7447'-48'- LT. TIH to 7473', set pkr. Test RBP to co displace any acid left in hole. Spot perfs @ 1100#. Pull pkr to 7377'. Set	<b>49'-50'-51'-52'-53'-54'-</b> 1000#, ok, release pkr. t acid over perfs. Close
<u>11-10-94</u>	to 3000 #. Held ok. 7315', set pkr. Press	<b>393' w/12 holes.</b> TIH to 7422', set RBP Release pkr. <b>Spot acid &amp; break down</b> sure to 500# (tried to reverse acid in <b>zing well w/500 gals 20% HCl NEFE</b> .	<pre>perfs @ 1100#. POOH to to tbg - could not catch</pre>
	to 3000 #. Held ok. 7315', set pkr. Press	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish <b>acidi</b> :	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish <b>acidi</b> :	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish <b>acidi</b> :	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish <b>acidi</b> :	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish <b>acidi</b> :	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
Continued	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish <b>acidi</b> : on page 2	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
Continued	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish <b>acidi</b> :	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
Continued	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish acidi: on page 2	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch
Continued 14. I hereby or Signed (This spece	to 3000 #. Held ok. 7315', set pkr. Press fluid). Finish acidi: on page 2 entify that the foregoing is true and correct Dominic J. Bazile	Release pkr. Spot acid & break down sure to 500# (tried to reverse acid in zing well w/500 gals 20% HCl NEFE.	perfs @ 1100#. POOH to to tbg - could not catch

\*See Instruction on Reverse Side

SLAINS PETROLEUM OPERATING CC. Y 415 WEST WALL, SUITE 1000, MIDLAND, TEXAS 79701 1125' FSL & 520' FWL Sec 35, T23S, R37E, Unit M E. C. Hill 'B' Federal #11 Teague Devonian Lea Co., NM

- 11-14-94 Release pkr. RIH to 7471', set pkr. Acidize w/200 gal 20% NEFE HCl, 2000 gal SXE oil/acid emulsion, 200 gal 20% NEFE HCl at 3.8 BPM 1800 psi, dropping 1.3 SG ball sealers for a total of 12 ball sealers. Displace w/10# brine. ISIP vaccum. Pmax 2400 psi, Pmin 712 psi. Release pkr move down catch RBP. POOH to 7471' w/RBP. Test plug, would not hold, reset RBP 4' higher, tested to 3000 psi, held. Wait on more acid & oil. Set pkr @ 7418'. Resume acidizing second zone, well communicated. Close csg, finish acidizing w/200 gal 20% NEFE HCl, 4000 gal SXE oil/acid emulsion, 200 gal 20% NEFE HCl at 2.9 BPM , 2600 psi, dropping 1.3 SG ball sealers for a total of 24 ball sealers. Displace w/10# brine. ISIP 1000 psi, 5 min 320 psi, 10 min 68 psi, 15 min 0 psi, Pmax 3030 psi, Pmin 2200 psi. Catch RBP. TOOH, Hook up pump truck, catch fluid w/50 BBLS 10# brine. Pump additional 110 BBLS 10# brine. Pump was 1400# @ 2-1/2 BPM. Circ possibly 5 BBLS acid out of tbg. Took 48 BBLS to catch fluid.
- 11-19-94 POOH w/tbg & model R pkr. RU WLT. TIH & log CBL from 7600' to 7200'. RIH, set CIBP @ 7424'. PU 5-1/2" x 2-3/8" RTTS pkr (Howco). TIH, set pkr @ 7420'. RU Dowell, load tbg, test CIBP, did not hold. Pull up hole above perfs. Load csg, test pkr, held. Release pkr. POOH. RU WLT, RIH, dump 10' cement on top of CIBP.
- 11-20-94 PU Howco RTTS tool. TIH to 7410', set pkr, test CIBP, leak, reset pkr, test RBP, held 1500#. POOH to 7291'. Establish rate 2-1/2 BPM @ 1100#. Mix 100 sx Class C, squeeze well w/hesitation squeeze to 1000#, 65-1/2 sx in formation. Reverse out, clean. Pull to 6469' w/pkr. Reverse again. Pressure to 500#, held good. SI w/500#.
- <u>11-21-94</u> Pressure test squeeze from 7383' to 7393' to 500#'s, held good 1/4 hr. Start drilling on cmt plug & CIBP. CIBP went down hole to 7447', stopped. Continue drlg. Drill up rest of CIBP. Start drlg cmt. Drill down to 7493', fall free. Run 2 more jts, circ clean. POOH w/4 stds, SDFN. Cmt all hard.
- 11-22-94 Arrive on location. Continue in hole w/tbg, tag TD @ 7705'. Circ hole w/2% KCl water. Hole is clean. POOH w/tbg, LD BHA. RU WLT. TIH w/4" select fire csg gun, perf 1 JSPF as follows: 7447' - 7454' (8 holes), 7459' - 7463' (5 holes), total of 13 holes. RD WLT. PU 5-1/2 x 2-3/8" Model R pkr. TIH to 7422', set pkr. Tie onto tbg, load hole w/27 BBLS KCl water, pump into zone w/only slow bleed off. Bled from 1000# to 500# in 45 seconds. RD pump truck. Start swabbing, swab tbg dry. RU acidizers. Bullhead 500 gals 7-1/2% NEFE acid into perfs (7447' - 7463', 13 holes), max psi 1400, min psi 900, test lines to 1600 psi, holding.
- <u>11-25-94</u> Acidize w/750 gals 15% NEFE acid, 33.5 BBLS of flush, avg rate 1.45, max rate 1.6, min rate 1.3, avg psi 1260, max psi 1463, min psi 1058.
- 11-29-94 Set Lufkin Mark II 228-213-100 pumping unit. Started well pumping to test treater @ Hill central tank battery at 7:00 p.m. 11-29-94.

## CODAGES OFFICE