

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-35125
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	F.B. DAVIS
8. Well No.	10
9. Pool Name or Wildcat	NORTH TEAGUE TUBB
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3329'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	PO BOX 3109, MIDLAND, TX 79702
4. Well Location	Unit Letter <u>C</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line Section <u>8</u> Township <u>23-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3329'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ COMPLETION DATA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-08-01/5-21-01: WAIT ON LOCATION.
5-22-01: WELL FLANGED UP. SWAB. REL PKR. TIH W/PMP & RDS. SN @ 7054. TA @ 6310. MUD JT @ 7085. FLANGED UP W/18 PTS TENSION. LOAD WELL & STROKE PUMP W/RIG.
5-24-01: LOAD TBG & PSI TEST TO 500. BLEED OFF TO 200 PSI. TIE IN ELECTRICITY & PUT WELL ON TEST.
5-26-01: START PUMP. SPACE OUT RDS. TURN ON PUMP JACK & BALANCE.
5-30-01: WELL PUMPED 6 BO, 35 BW, & 0 MCF. THEN QUIT PUMPING. MECHANICAL PROBLEMS.
6-10-01: CHANGE OUT PUMP JACK.
6-28-01: MIRU KEY #311 & REV UNIT. UNSEAT PUMP & TOH. NDWH. NUBOP.
6-29-01: TIH W/CIBP & SET @ 6530'. TIH W/CMT BAILER & DUMP 35'CMT ON CIBP. TA ABO. RDWL. TIH W/2 7/8" TBG OPEN ENDED TO 6390'. CIRC W/150 BBLS 2% KCL WTR. TEST & CHART CSG & CIBP TO 560# FOR 30 MINS-OK.
6-30-01: TIH & RUN PDC LOG FR 6483-5800. TIH W/PERF GUN & PERF 5 1/2" CSG IN TUBB FORMATION FR 6406-10,6426-30,6390-94, 6398-6402,6360-62,6368-78,6308-12,6332-40. TIH W/PKR, SN. PSA 6214.
7-03-01: ACIDIZE TUBB PERFS W/4000 GALS 15% HCL. RU SWAB. FL @ SURF. END FL @ 2600. REL PKR & LOWER TBG TO 6460. PKR SWINGING @ 1874'.
7-04-01: FRAC TUBB PERFS 6308-6430 W/142,940# OF 20/40 JORDAN IN 80,934 GALS OF 40#,35# & 30# XLG. FLUSH TO TOP PERF W/147 BBL YF130.
7-06-01: FLOW TO FRAC TANK. TIH W/BIT & PU WS TO 6196'. RU REV UNIT. DISPL W/130 BBLS 2% KCL. LOWER TOOLS & TAG @ 6333. C/O FRAC SAND TO 6495.
7-07-01: LOWER TBG TO 6495'. TIH W/TBG, SN, & TAC. TBG @ 6433. SN @ 6400. TAC @ 6178. TAG SAND FILL @ 6481. SET TAC. LAND TBG. NDBOP. NUWH. WELL FLOWING.
7-08-01: TIH W/FILTER, PUMP & RDS. PUMPING @ 10:30 AM.
7-14-01: ON 24 HR OPT. PUMPING 86 BO, 242 BW, & 213 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 9/25/01
TYPE OR PRINT NAME J. Denise Leake Telephone No. 915-688-4752

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER

DATE _____

APR 03 2002