November 1983) Formerly 9–331)	UN ED STATES PARTMEN OF THE INT BUREAU OF LAND MANAGEM	ERIOR (Other instructions	re Expires August 31, 1985 5. LEASE DESIGNATION AND SEELAL NO.
SUNDRY	NOTICES AND REPORT or proposals to detill or to deepen or p APPLICATION FOR PERMIT-" for su	S ON WELLS	LC-061936-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
······································			7. UNIT AGREEMENT NAME
WELL XX WELL OTHER			Cotton Draw Unit
NAME OF OPERATOR			8. FARM OR LEASE NAME
Texaco Inc.			Cotton Draw Unit
ADDRESS OF OPERATOR			9. WBLL NO.
P.O. Box 730, Hobbs, NM 88240 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 22001 DBZ 6 2001 DBZ (10 the second s			34
			10. FIELD AND POOL, OR WILDCAT
			Paduca Delaware
330' FSL & 330' F	FEL (Unit Letter P)		11. SBC., T., B., M., OR BLK. AND SURVEY OR AREA
			Sec. 9, T-25-S, R-32-E
4. PERNIT NO. 15. ELEVATIONS (Show whether DF, ET, GR, etc.) 20. 025 - 021 (12. COUNTY OR PARISE 18. STATE	
30-025-08168	3456	DF	Lea NM
	eck Appropriate Box To Indicate		
	DF INTENTION TO:	8080	EQUENT REPORT OF :
TEST WATER SHUT-OFF	PCLL OB ALTER CASING	WATER SHUT-OFF	BEPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CARING
SHOOT OR ACIDIZE	ABANDON®	SHOOTING OR ACIDISING	ABANDONMENT [®] X
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		' Completion or Record	its of multiple completion on Well apletion Beport and Log form.) es, including estimated date of starting any
<pre>2) WIH w/2-1/16" @ 4500'. Tag</pre>	'd top @ 4140'. POH.		Spt 10 sx cmt (360') plug
 WIH w/2-1/16" @ 4500'. Tag Ran free poin Cir 10# brine Spt 2nd plug @ 390'. Tag' 	'tbg. Load 2-7/8" csg 'd top @ 4140'. POH. ut. Cut off 2-7/8" csg mud.	@ 995'. Pld 32 jts 2 Tag'd top @ 837'. Sp plug 15 sx (60') @ 60	2-7/8" csg. WIH w/2-1/16"
 WIH w/2-1/16" @ 4500'. Tag Ran free poin Cir 10# brine Spt 2nd plug @ 390'. Tag' 	'tbg. Load 2-7/8" csg d top @ 4140'. POH. t. Cut off 2-7/8" csg mud. 30 sx (213') @ 1050'. d top @ 270'. Spt 4th t off WH. Instld marke	@ 995'. Pld 32 jts 2 Tag'd top @ 837'. Sp plug 15 sx (60') @ 60	2-7/8" csg. WIH w/2-1/16" ot 3rd plug 40 sx (120') of to surface.
 2) WIH w/2-1/16" @ 4500'. Tag 3) Ran free poin Cir 10# brine 4) Spt 2nd plug @ 390'. Tag' 5) Rig down. Cu 	'tbg. Load 2-7/8" csg 'd top @ 4140'. POH. at. Cut off 2-7/8" csg mud. 30 sx (213') @ 1050'. d top @ 270'. Spt 4th at off WH. Instld marked area	@ 995'. Pld 32 jts 2 Tag'd top @ 837'. Sp plug 15 sx (60') @ 60	2-7/8" csg. WIH w/2-1/16" ot 3rd plug 40 sx (120') of to surface.
 WIH w/2-1/16" @ 4500'. Tag Ran free poin Cir 10# brine Spt 2nd plug @ 390'. Tag' Rig down. Cu No water basin in No water basin in I bereby certify that the foregram	<pre>tbg. Load 2-7/8" csg d top @ 4140'. POH. t. Cut off 2-7/8" csg mud. 30 sx (213') @ 1050'. d top @ 270'. Spt 4th t off WH. Instld mark area area </pre>	@ 995'. Pld 32 jts 2 Tag'd top @ 837'. Sp plug 15 sx (60') @ 60 er. Cleaned locn.	2-7/8" csg. WIH w/2-1/16" ot 3rd plug 40 sx (120') o' to surface.
 2) WIH w/2-1/16" @ 4500'. Tag 3) Ran free poin Cir 10# brine 4) Spt 2nd plug @ 390'. Tag' 5) Rig down. Cu 5) Rig down. Cu No water basin in No water basin in I hereby certify that the foregrees SIGNED A A Lea	tbg. Load 2-7/8" csg d top @ 4140'. POH. t. Cut off 2-7/8" csg mud. 30 sx (213') @ 1050'. d top @ 270'. Spt 4th t off WH. Instld marked area area te office use)	@ 995'. Pld 32 jts 2 Tag'd top @ 837'. Sp plug 15 sx (60') @ 60 er. Cleaned locn.	2-7/8" csg. WIH w/2-1/16" ot 3rd plug 40 sx (120') of to surface.
 2) WIH w/2-1/16" @ 4500'. Tag 3) Ran free poin Cir 10# brine 4) Spt 2nd plug @ 390'. Tag' 5) Rig down. Cur 5) Rig down. Cur No water basin in No water basin in I hereby certify that the foregrees signed A de a (This space for Federal or State a definitions of APPROVAL, Approved BT CONDITIONS OF APPROVAL, Approved a definition of a	tbg. Load 2-7/8" csg d top @ 4140'. POH. t. Cut off 2-7/8" csg mud. 30 sx (213') @ 1050'. d top @ 270'. Spt 4th t off WH. Instld marked area area to off true and correct TITLE	@ 995'. Pld 32 jts 2 Tag'd top @ 837'. Sp plug 15 sx (60') @ 60 er. Cleaned locn.	2-7/8" csg. WIH w/2-1/16" ot 3rd plug 40 sx (120') o' to surface.
 2) WIH w/2-1/16" @ 4500'. Tag 3) Ran free poin Cir 10# brine 4) Spt 2nd plug @ 390'. Tag' 5) Rig down. Cu 5) Rig down. Cu 5) Rig down. Cu No water basin in No water basin in I hereby certify that the foregometry signed	tbg. Load 2-7/8" csg d top @ 4140'. POH. t. Cut off 2-7/8" csg mud. 30 sx (213') @ 1050'. d top @ 270'. Spt 4th t off WH. Instld marked area area te office use)	@ 995'. Pld 32 jts 2 Tag'd top @ 837'. Sp plug 15 sx (60') @ 60 er. Cleaned locn.	2-7/8" csg. WIH w/2-1/16" ot 3rd plug 40 sx (120') o' to surface.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Ç.