## UNTTED STATES N.' Oil Cons. Division DEPARTM [ OF THE INTERIOR P.O. Box 1980 BUREAU OF LAND MANAGEMENT FORM APPROVED Hobbs, NM 8824 Budget Bureau No. 1004-0135 Expires March 31, 1993 5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. LC061936 Use "APPLICATION FOR PERMIT-" for such proposals 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE N/A 7. If Unit or CA, Agreement Designation 1. Type of Well Gas Well Other N/A Well 8. Well Name and No. Name of Operator **DEVON ENERGY CORPORATION (NEVADA)** E.F. Ray "B" NCT-1 #1 3. Address and Telephone No. 9. API Well No. 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611 30-025-08173 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage. Sec., T., R., M., or Survey Description) 660' FSL & 1980' FEL, Sec. O-10-T25S-R32E Paduca (Delaware) 11. County or Parish, State Lea Cnty, New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent X Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

In May, 1997 we plan to permanently Plug and Abandon the E.F. Ray "B" NTC-1 #1 by turnkey operations. The plugging company we plan to use is Dawson Production Services.

Attached please find the following.

- 1. Procedure to Permanently Plug and Abandon Well
- 2. Current well bore schematic (well is SI)
- 3. Proposed schematic of well bore P&A

14. I hereby certify that the foregoing is true and correct Candace R. Graham AND Title Engineering Technician Date \_\_\_\_\_May 22, 199' (This space for Federal or State office use) (ORIG. SGD.) GARY GOURLEY PETROLEUM ENGINE Approved by Title Conditions of approval, if any

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Form	3160-5
(June	1990)

RECENTED

MAY 27 97

SLM ROSWELL. NM

## DEVON ENERGY CORPORATION Interoffice Correspondence

TO: Rick Clark

FROM: W. M. Frank

RE: Procedure to Permanently Plug & Abandon Well E.F. Ray "B" NTC-1 #1 660' FSL & 1980' FEL Section 10-T25S-R32E Lea County, New Mexico

Well Data: Elevation - 3452' GL 3461' KB.

TD - 4800' Driller

Casing - 7 5/8" 24# @ 313' Cemented to Surf - 4 1/2" 9.5# @ 4799' Cmt w/150 sx

Note: Location may have H2S present. All personnel on location must have H2S certification. Conduct H2S safety meetings at each stage of procedure where gas may reach surface. <u>Make sure that all personnel are aware of safety procedures.</u>

## Procedure

- 1. MIRU DDPU. Haul in  $\pm 4800^{\circ}$  of 2 3/8" tubing.
- 2. ND wellhead and NU BOPE. Attempt to release packer (make and model not known). If packer releases, POOH laying down tubing and packer. If packer does not release MIRU electric line unit. TIH w/freepoint tool, establish freepoint, and cut tubing at free point. RDMO electric line unit. POOH laying down tubing.
- 3. TIH w/CIBP PU tubing to 4700'. Set CIBP and circulate hole w/9.5 ppg mud. Pressure test casing to 500 psig. Spot 5 sxs "C" cement directly on top of CIBP.
- 4. POOH standing back 3200' of tubing, lay down remainder.
- 5. ND BOPE and Larkin head. Latch onto 4 1/2" casing and work to establish free point.
- 6. MIRU electric line truck and pack off. TIH w/jet cutter and cut 4 1/2" casing 200' above calculated free point. RD electric line truck.

LC020041 E.F. Ray "B" NTC-1 #1 Lea County, New Mexico Procedure to Permanently P&A May 21, 1997 Page Two

- 7. POOH laying down 4 1/2" casing. Tally casing during lay down process. Make sure to fill hole w/9.5 ppg mud during trip out. Displacement is 3.5 bbls per thousand feet of pipe.
- 8. TIH w/2 3/8" tubing to casing stub. Attempt to enter casing stub w/tubing. If possible go down 50' into stub and spot 25 sxs Class "C" balanced plug.
- 9. POOH laying down tubing to 1150' (top of salt). Spot 25 sxs Class "C" balanced plug.
- 10. POOH laying down tubing to 370' (50 below shoe). Spot 25 sxs Class "C" balanced plug.
- 11. POOH laying down tubing to 30', circulate cement to surface. Lay down tubing joint.
- 12. Cut wellhead off 3' below ground level. Weld plate over casing stub and install dry hole marker. RDMO plugging equipment. Clean and reclaim location as necessary to comply with BLM requirements.





RAYB1A.SCH