

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions
reverse side)
HOBBS, NEW MEXICO

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICE AND REPORTS ON WELLS

(Do not use this form for a permit to deepen or plug back to a different reservoir.
Use Form 3160-6 for "PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ Shut-in	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME WELLS A
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit H 2310' FNL & 990' FEL	10. FIELD AND POOL, OR WILDCAT Talmat Yates 7 Rivers
14. PERMIT NO. 30-025-09732	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11-255-36E
15. ELEVATIONS (Show whether DF, HT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANE ☐
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other)	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and spaces pertinent to this work.)*

- ① MIRU, Spot a 200' balanced cmt plug in the open hole section (3120') by pumping 50 sxs class "C" w/ 3% CaCl₂ w/ 1/4 #/sack floccle.
- ② POOH w/ workstring to 3050'. Circ. 3 bbls wtr down workstring.
- ③ POOH w/ workstring to 2950'. WOC for at least 4 hrs.
- ④ TIH w/ workstring and tag top of cmt plug. If top of plug is below 3000', spot another 25 sxs plug on bottom.
- ⑤ Set CIBP @ 2900'. Spot 25 sxs class "C" w/ 2% CaCl₂. Perf @ 1150' w/ 2 JSPE.
- ⑥ Pump 650 sxs class "C" cmt w/ 2% CaCl₂ down 8 5/8" prod. csg. Displace * w/ 70 bbls wtr. Shut in 12 hrs min. and run temp. survey to find TO.
- ⑦ Spot surface cmt plug w/ 100 sxs class "C" w/ 2% CaCl₂.
- ⑧ Cut off csg 3' below ground level, install P & A marker, clean location and rig down.

* 6a) Circ. annulus to surf & cover all perfs w/ cmt.

18. I hereby certify that the foregoing is true and correct

SIGNED

Kevin Logg

TITLE

Administrative Supervisor

DATE

6-2-86

(This space for Federal or State office use)

APPROVED BY

Mark Brown

TITLE

AREA MANAGER

DATE

6-13-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side