

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP DATE
(Other instructions
reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ <u>temp. shut-in</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-032582 (A)</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>Unit D</u> <u>660' FNL & 330' FWL</u>	8. FARM OR LEASE NAME <u>Wells A</u>
14. PERMIT NO. <u>30-025-09744</u>	9. WELL NO. <u>6</u>
15. ELEVATIONS (Show whether DF, ST, GR, etc.)	10. FIELD AND POOL, OR WILDCAT <u>Talmat Yates 7 Rivers</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 12-255-36E</u>
	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and names pertinent to this work.)

- ① MIRU, and set 5 1/2" CIBP @ 3390'.
- ② Load hole w/ water and press. test csq to 500 psi.
- ③ Spot 100' cmt plug on top of CIBP w/ 10 sxs Class "C" w/ 2% CaCl₂.
- ④ Spot 100' cmt plug from 2715'-2615' w/ 10 sxs Class "C" w/ 2% CaCl₂.
- ⑤ Spot 100' cmt plug from 1200'-1100' w/ 10 sxs Class "C" w/ 2% CaCl₂.
- ⑥ Perf csq @ 60' w/ 2 JSPF. Pump and circulate 25 sxs Class "C" cmt w/ 2% CaCl₂ to surface.
- ⑦ Cut off csq 3' below ground level and install P & A marker
- ⑧ Rig down and restore location.
- ⑨ A proposed P & A sketch is attached.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE

6-9-86

(This space for Federal or State office use)

APPROVED BY

TITLE

AREA MANAGER

CARLSBAD RESOURCE

DATE

6-13-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side