

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
Other instructions on
reverse side

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Maralo, Inc.

3. ADDRESS OF OPERATOR
P. O. Box 832, Midland, Texas 79702-0832

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FSL & 1830' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF RT, CR, etc.)
3029'

5. LEASE DESIGNATION AND SERIAL NO.
LC-032581-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Sholes "B"

9. WELL NO.
3

10. FIELD AND POOL OR WILDCAT
Jalmat Yates 7Riv Tan

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 25, T-25-R-36

12. COUNTY OR PARISH
Lea

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set CIBP @ 3000' w/35' cement on top to 2980'.
2. Load hole with 10#/gal mud-laden fluid using 25# gel/bbl.
3. Determine free-point of 5 1/2" casing. Cut and pull free casing.
4. If free-point is below 425', place 100' cement plug across casing cut. If free-point is above 425', perf 5 1/2" casing @ 450' and squeeze 100' cement outside casing & leave 100' cement inside casing.
5. Set 100' cement plug across 10 3/4" surface casing shoe from 375' to 475'.
6. Using 10 sacks cement, set surface plug.
7. Remove wellhead, cut off casing & weld plate on casing.
8. Clean up location.
9. Place dry hole marker at location.

REASON FOR ABANDONMENT:

Well is uneconomical to produce. There are no other prospective zone to open.

18. I hereby certify that the foregoing is true and correct

SIGNED Brenda Hoffman

TITLE Agent

DATE 10-16-87

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

11-17-87

*See Instructions on Reverse Side