

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
ILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-1167

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Maralo, Inc.

Address of Operator
P. O. Box 832, Midland, Texas 79702-0832

Location of Well
UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 36 TOWNSHIP 25-S RANGE 36-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Shell "A" State

9. Well No.
1

10. Field and Pool, or Wildcat
Jalmat Yates 7 Rivers Tan

15. Elevation (Show whether DF, RT, CR, etc.)

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
JLL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

1. Notify New Mexico Oil Conservation Commission
2. Set CIPB @ 3000' w/25 cement on top to 2980'.
3. Load hole with 10#/gal mud-laden fluid using 25# gel/bbl.
4. Set 100' cement plug across 7" casing shoe from 2834' to 2934'
5. Determine free-point of 5 1/2" casing. Cut and pull free casing.
6. Place 100' cement plug across 5 1/2" casing cut.
6. Place 100' cement plug across 5 1/2" casing cut.
7. Determine free-point of 7" casing. Cut and pull free casing.
8. Place 100' cement plug across 7" casing cut. If free-point is above 305', perf 7" casing at 350' and squeeze 100' cement outside of casing and leave 100' cement inside of casing.
9. Set 100' cement plug across 10 3/4" shoe from 255' to 355'.
10. Using 10 sacks cement, set surface plug.
11. Remove wellhead, cut off casing and weld plate on casing.
12. Clean up location.
13. Place a metal dry hole marker at location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Brenda Callman

TITLE Agent

DATE 5-19-87

915 684-7441
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY R N
EDITIONS OF APPROVAL, IF ANY:

TITLE

DATE MAY 22 1987