## STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL	CONSERVATION	DIVISION
<b>~</b>	<b>C</b> - 7 - 1 - 1	

	OIL CONSERVATION DIVISION	Samu C 102 .	
40. 07	P. O. BOX 2088	Form C-103 Revised 10-1-70	
DIS	SANTA FE, NEW MEXICO 87501	_	
SANTA	0+6-NMOCD-Hobbs 1-Laura Richardson	5a. Indicate Type of Leuse	
PILE	- I mile	State Fee XX	
U.S.G.		5. State Oil & Gas Lease No.	
OPER	OFFICE 1-Engr. DBW		
OPEA	1-Foreman CRM	mmmmm	
	SUNDRY NOTICES AND REPORTS ON WELLS		
10.0	SUNDRY NOTICES AND KEPOKIS OF THE STATE OF PLUG NACK TO A DIFFERENT RESERVOIR.  HOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DEEPEN OR PLUG NACK TO A DIFFERENT RESERVOIR.  HOT USE THIS FORM FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)		
(60	USE "APPLICATION FOR PERMIT	7. Unit Agreement Name	
1.	CAS TV		
WELL	WELL XX OTHER-	8. Form or Lease Name	
2. Name of C	perator	Cooper Jal Unit	
(	Setty Oil Company	9. Well No.	
3. Address	of Operator	7: 1:244	
	P.O. Box 730 Hobbs, NM 88240	10. Field and Pool, or Wildcat	
4. Location	7 NO 11	Jalmat	
	T 1980 SOUCH LINE AND FEET FROM	THE THE THE THE THE	
UMIT L	CYTER		
	East Line, section 18 township 24S range 37E NMPM		
THE			
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
	3309' D.F.	Lea \\\\\\\	
		ther Data	
16.	Check Appropriate Box To Indicate Nature of Notice, Report or O	IT REPORT OF:	
	NOTICE OF INTENTION TO:	TI REFORT OF	
	Morros -		
,	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING (	
	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
	CHANGE PLANS CASING TEST AND CEMENT JOB	. г	
PULL OR A	LTER CABING OTHER		
OTHER	·		
	the Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	ng estimated date of starting any propos	
17. Descr	be Proposed or Completed Operations (Steam)		
1.	Rig up pulling unit and install BOP.	•	
<u> </u>	Pull rods, pump and tubing.	201 501	
	$\sim$ 1 $\sim$ 2 $\sim$ 2 $\sim$ 2 $\sim$ 3		
3.	Perforate Jalmat gas zone at 2550 , 250 , 86', 99', and 3205'. 70', 90', 3100', 37', 52', 62', 69', 78', 86', 99', and 3205'.		
	Run RBP and RTTS packer, set RBP @ 3220 +.	•	
4.	Run RBP and RTTS packer, see the second see the second sec		
5.	Spot 350 gals. 15% NE-FE HCL across perfs.	ackside to	
6.	Spot 350 gals. 15% NE-FE HCL across peris.  Raise and set packer at 2775' +, reverse 5 barrels water down barrels.	•	
	clear acid out of casing. Acidize perfs with additional 2650 gal. of 15% NE-FE HCL and 30	ball sealers,	
7	Acidize perfs with additional 2650 gal. Of 13% NE 12 her and 55		
	nump at 4-5 BPM.		
0	Flow and/or swab Jalmat perfs		
	11 1 1 1 1 2		
9.	Re-run tubing, rods and pump and place on production.		
ΤΟ.	KG-Tuil contrid / Todo I		

information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the

DATE May 20, 1983

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

..MAY 25 1983

MAY 24 1983 MORAS OFFICE