NO. OF COPIES RECEIVED		
DISTRIBUTION	HOBBS on	Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	4 - NMOCC	Effective 1-1-65
U.S.G.S.		
	-1 - File 30 AM G	5a. Indicate Type of Lease
OPERATOR		State Fee
		5. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR USE "TAPPLIC	DRY NOTICES AND REPORTS ON WELLS proposals to drill or to deepen or plug back to a different reservoir. ation for permit -** (form C-101) for such proposals.)	
OIL GAS	Sour (Korosals)	7. Unit Agreement Name
2. Name of Operator	OTHER.	
		8. Farm or Lease Name
Getty Oil Company	·	Fowler Hair
3. Address of Operator		9. Well No.
Box 249, Hobbs, N	• Mex.	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	330 FEET FROM THE SOUTH LINE AND 330 FEET	· · · · · · · · · · · · · · · · · · ·
THE LINE, SEC	TION 25 TOWNSHIP 218 RANGE 378 N	
	TOWNSHIP RANGE N	^{MPM.} (()))))))))))))))))))))))))))))))))))
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
^{16.} Check	Appropriate Box To Indicate Nature (N. : D	
	Appropriate Box To Indicate Nature of Notice, Report or	
	SUBSEQU	ENT REPORT OF:
PERFORM REMEDIAL WORK		
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
7. Describe Proposed or Completed (Operations (Clearly state all pertinent details and simple in the state of the stat	

work) SEE RULE 1903.

Pulled tubing and packer. Set cast-iron bridge plug at 2927'. Dumped 12' essent on tep. PBTD at 2915'. Filled casing with 72 bbls. treated brine. Tested easing with 1000# for 30 minutes, CK. Ran bit and casing scraper to PBTD. Spotted 200 gals. 15% LST acid. Perforated 5-1/2" casing from 2536-46, 2570-80, 2605-15, and 2646-56' with one jet per foot. Treated with 500 gals. 15% LST acid, followed with 250# salt in 4 bbls. gelled brine, them 750 gals. 15% LST acid, followed with 400# salt in 6 bbls. gelled brine, them 750 gals. 15% LST acid. Max. press. 2500#, min. press. 1800#. ISIP 1500#. 14 hr. SITP 1450#. Bled eff. In 1-1/2 hours swabbed 11 BLW and tubing dry. Shut down end hour, 400' fluid in tubing. 16 hour SITP, vacuum. 800' fluid entry into tubing. Swabbed dry, slight show of gas. In 26 hours with tubing open to separater, well had 400' fluid entry into tubing. 1st run with sweb recovered 350', 2nd run, recovered 50' and tubing dry, ne fluid en 3rd run with sweb, no show of oil or gas. Total fluid recovery 30.5 BLW. 15 hour shut down with tubing open to separator, still need to recover 56.50 BLW. Shut well in, pending P & A.

. I hereby certify that the information above is true and cor Original Signed By		-	
NEDC.L. WADE		Area Supt.	DATE May 28, 196
NOVED BY	TITLE		DATE



	1	
NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION	HOBBS OFFICE O.C.C.	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State 🔄 Fee. 🕱
OPERATOR		5. State Oil & Gas Lease No.
SUNDR (DO NOT USE THIS FORM FOR PRO USE "APPLICAT	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7, Unit Agreement Name
OIL GAS WELL WELL	OTHER-	
2. Name of Operator		8. Farm or Lease Name
Getty Oil (Company	Fowler Hair
3. Address of Operator		9. Well No.
Box 240 H	bbs, New Mexico	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	330FEET FROM THE South LINE AND 330FEET FRO	
	IN 25 TOWNSHIP 24S RANGE 37E NMP	
	15. Elevation (Show whether DF, RT, CR, etc.)	12. County
Check A NOTICE OF IN	Appropriate Box To Indicate Nature of Notice, Report or O TENTION TO: SUBSEQUEN	ther Data
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING
OTHER	OT HER	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is currently NIO. It is proposed to plug off the Queen zone at 3260' and perforate the Yates Gas zone as follows:

Set CI BP at approximately 2900' with minimum of 10' of cement on top. Run Gamma Ray-Neutron collar log from approximately 1900' to 2900'. Run tubing with bit and scraper and spot 200 gals 15^d HCL double inhibited acid over interval to perforate. Perforate with 4" Dicone casing gun (0.42" holes) with one jet/ft. according to porosity intervals from Gamma Ray-Neutron log, approximately 2536-46, 2570-80, 2605-15' and 2645--55'. Run tubing and set treating packer above perforations at approximately 2400'. Treat with 2000 gals. LST acid and rock salt.

18. I hereby certify that the information above is true and comp Original Signed By	plete to the best of my knowledge and belief.	
SIGNEDC. L. WADE	- TITLE Area Superintendent	DATE May 19, 1969
	SUPERVISOR DISTRICT .	MAY 20 1969
CONDITIONS OF APPROVAL, IF ANY:		