	~	P.O-80X	1980 IEW MEXICO 88240		
	• •	STATES F THE INTERIOR D MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM ~ 0321613 5. Construction of the state of the series of the serie		
	7. If Unit or CA, Agreement Designation				
<ol> <li>Type of Well</li> <li>Oil</li> <li>Gas</li> <li>Well</li> <li>Well</li> <li>Well</li> <li>Well</li> <li>Well</li> <li>Well</li> <li>Well</li> <li>Gas</li> <li>Well</li> <li>Gas</li> <li>Well</li> <li>Gas</li> <li>Well</li> <li>Gas</li> <li>Well</li> <li>Gas</li> <li>Gas<td>8. Well Name and No. Jack B-26 No. 1 9. API Well No. 300-25-1123200 10. Field and Pool, or Exploratory Area Justis Blinebry 11. County or Parish, State Lea MM ORT, OR OTHER DATA</td></li></ol>	8. Well Name and No. Jack B-26 No. 1 9. API Well No. 300-25-1123200 10. Field and Pool, or Exploratory Area Justis Blinebry 11. County or Parish, State Lea MM ORT, OR OTHER DATA				
TYPE OF	SUBMISSION	N			
	of Intent ient Report bandonment Notice	Abandonment Abandonment Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form		

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This shut-in wellbore has either tested or produced in the Yates, Seven Rivers, Queen, Glorietta, and Blinebry formations. Reservoir engineering studies indicate that there is no further producing potential for this well and propose to plug and abandon it according to the attached procedure and schematic.



14. 1 hereby centry that the foregoing a true and forrect Signed	Tide Sr. Conservation Coordinator	Date
(This spect for Federal of State office use) Approver by		Date 3/18/94

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



MAR 2 2 1914



•

# JACK B-26 No 1 PLUG AND ABANDONMENT

#### INTRODUCTION:

This well was SI when production went to zero in April 1993. A casing leak is suspected. Prior to shut-in, the well was producing a daily rate of 2 BO, 15 BW, and 23 MCFG (3-2-93 test). The well will be permanently plugged and abandoned.

#### WELL DATA:

Location: 660' FNL & 1980' FWL, Sec 26, T-24-S, R-37E, Lea County, New Mexico G.L. Elevation: 3210' KB Elevation: 3221'

#### EQUIPMENT:

Lufkin 114D w/ 20 HP Toshiba motor. Rods have been pulled. Tubing is still in hole. The pumping tee is bullplugged.

#### **REGULATORY:**

This well is completed in the Justis Blinebry Pool. Regulatory approval is required for this work.

OD (inchee)	WT (P91)	Grade	Drift ID (inch <del>es</del> )	Depth	Collapse @ 100% (psi)	Burst @ 100% (pei)	Capacity (bpf)	Capacity (ofpf)
10 3/4	40	Not Known		356'				
7	23	Not Known	6.241	3258'			0.0393	0.2210
5	15	Not Known	Not Known	3087'- 5758'			0.0188	0.1059
2 3/8	4.7	J-55	1.901	5649	8,100	7,700	.00387	0.0217

## CASING & TUBING SPECS:

NOTES: 1. DUE TO THE VINTAGE OF THE CASING AND THE LACK OF DATA IN THE RECORDS, USE CAUTION WHEN PUMPING OR PRESSURING-UP ON THE TUBULARS.

# 2. A TIGHT SPOT WAS REPORTED IN THE 5" LINER DURING WELL WORK IN 7/77 (SEE WELL HISTORY). THE DEPTH OF TIGHT SPOT WAS NOT GIVEN.

## **RECOMMENDED PROCEDURE:**

- 1. MIRU workover rig. Kill well if necessary. ND WH & NU BOPE. TFF and POOH with tubing.
- 2. RIH with 4 1/4" bit & 5" scraper on 2 7/8 " workstring to 5175'. POOH.

- NOTE: 1. Use Class C cement mixed at 14.8 ppg with 2% CaCL<sub>2</sub> for all cement work except final surface plug which will contain 18% CaCl<sub>2</sub>.
  - 2. For remainder of procedure use P&A brine 10 ppg brine with 25 lbs/bbl of salt gel.
- 3. RIH with 5" cement retainer & set at 5150'. Squeeze Blinebry perforations with 150 sxs cement. Pick up workstring and spot 25 sx (312') cement cap on retainer. Slowly PUH well above top of cement @ +/- 4838' and reverse cement out of workstring.
- 4. WOC. RIH tag TOC to ensure old Glorietta perfs (squeezed 10-68) are covered. **Record** tag depth. If Glorietta perfs are not covered spot additional cement as necessary. Circulate P&A brine (10 ppg brine with 25 lbs/bbl salt gel).
- 5. Shut rams on workstring and test casing to 500 psi. If leakoff occurs, RIH isolate leak and establish pump-in rate. Call information to engineering.

## NOTE: Leak may have to be cement squeezed.

- 6. POOH to 3,260'. Spot 25 sxs (33 cuft) cement to cover liner top. **Slowly** pick up well above top of cement @ +/- 3.020' and reverse out workstring. POOH.
- 7. Set CIBP at 2650' to isolate old Yates/Seven Rivers squeeze perfs. Spot 25 sxs cement cap on CIBP. Top of cement cap should be at +/- 2500'. **Slowly** POOH with workstring.
- 8. Perforate @ 400' with 4" HSC loaded with 4 JSPF @ 120° phasing.
- 9. RIH to 400' with 2 7/8" workstring. Establish injection rate through perfs and up 7" X 10 3/4" casing annulus. Pump 150 sxs Class C cement mixed at 14.8 ppg with 18% CaCl<sub>2</sub> taking returns through 7" casing valve. When cement circulates to surface, close valve and fill 7" casing to surface with 70 sxs cement.
- 10. If cement does not circulate to surface, pump 75 sxs down 7" X 10 3/4" annulus.
- 11. Cut off casing 3' below surface. Weld 1/4" thick metal plate on wellbore. Install P&A marker with well name and location inscribed on marker.
- 12. Restore location.

<u>2</u>/24/94

MAR 2 3 (994

-۱۰ ماتبار OFFICE

# WELLBORE DIAGRAM JACK B-26 NO. 1 NEW MEXICO FEDERAL UNIT



BY: S. F. SHEPARD

DATE: 06-12-91



DATE: 2/24/94