n 3160-5 cember 1989) Do not use this	DEPARTMEN BUREAU OF I SUNDRY NOTICES	TED STATES TOF THE INTERIOR AND MANAGEMENT AND REPORTS ON WELLS III or to deepen or reentry to a different reservoir. TPERMIT—" for such proposals	FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990 5. Lease Designation and Serial No. Fed #NM-14218 6. If Indian. Allottee or Tribe Name	
		IN TRIPLICATE	7. If Unit or CA. Agreement Designation	
Name of Operator	Exploration & Produ	ction Inc.	8. Well Name and No. C.C. Fristoe B Fed NCT-2 #2 9. API Well No. 30-025-11239	
Address and Telepic	ome No. ox 730, Hobbs, NM	38241-0730 (505) 393-7191	10. Field and Pool. or Exploratory Area	
P.U. DO	ootage, Sec., T., R., M., or Survey D	Langlie Mattix		
	er I, 1980 FSL, 660		II. County of Parish, State	
Section	6, T-24-S, R-37-E		Lea County, NM	
		(1) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA	
		TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION		
ТҮРЕ	OF SUBMISSION	× I	Change of Plans	
	tice of Intent	Abandonment		
S	bsequent Report	Plugging Back Casing Repair	Non-Routine Fracturing Water Shut-Off	
- I r	nal Abandonment Notice	Altering Casing	Conversion to Injection	
		(Note: Report results	s of multiple completion on Well Completion or t and Log form.)	
		Ill pertinent details, and give pertinent dates, including estimated date of start	ing any proposed work. If well is directionally drilled.	
i. Describe Propose: give subsurfac	or Completed Operations (Clearly state te locations and measured and true ver	ill pertinent details, and give pertinent action in the work.)*		
		PROPOSED PROCEDURE		
		4 hours prior to commencement of rods and pump. Install BOP and , bit and 7" casing scraper. Cl		

- 2)
- 3) By wireline, set CIBP at 3225'.
- 4)
- 5)
- 6)
- By Wilerine, set CIDF at 3225. Load hole with salt gel mud; 10# brine and 25# gel/ Bbl. POH. GIH with work string. Pump' 50', 10 sx, cement on top of CIBP. Move up hole and pump 100' plug, 20 sx, from 2300'-2400'. Move up hole. Pump 300' plug, 60 sx, from 1004'-1304' and 20 sx from 100' to the surface. Lay down work string and ND BOP. 7)
- Cut off wellhead and install dry hole marker. Clean location.
- 8) Restore surface as per Federal regulations. 9)

(see reverse)

4. I hereby certify that the foregoing is true and correct Signed Diff John Sow	Title	Engr. Asst.	Date7 24 91
(This space for Federal or State office weil and	Title	A MARTINE CONTRACTOR	Date 8.5 41
Approved by	100		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false. Fictitious or fraudulent statements or representations is to any matter within its jurisdiction.

Texaco Inc.	WELL DATA SHEET PO-113 (5/91) (5/91) Lease: C.C. Fristoe B Fed NCT-2 #2 Sec./Twn/Rng: Unit I, Sec 26, T-24-S, R-37-E
SCHEMATIC	Lea County, New Mexico
Gr 1254' 2015' 2015' 3250' Tops: Salt 1237'-2344' Yates 2489' Queen 3250'	TABULAR DATA Set atSurface Casing:Set atSize9.5/8.32.34Cemented withSize9.5/8.32.34Cemented withTOCsurface' determined byHole Size12.1/4"Comp. DateHole Size12.1/4"Comp. DateIntermediate casing:Set atSizeCemented withNONECemented byToc' determined byNole SizeSet atSizeSet atProduction Casing:Set atSizeCemented withMole SizeCemented withHole Sizedetermined byHole Size8.3/4"Open Hole Interval:3250 ' toSizeNitro Shot200 Ots SOWE \$1, 3359' - 3429'

FOOTAGE LOCATION: <u>1980 FSLx 660 FEL</u>	AND ABANDON DATA PO-113 LEASE: C.C. Fristoe B Federal NCT-2 #2 ec./Twn/Rng: Unit I. Sec 26. T-24-S. R-37-E tested 1000#. 1 hr
Gr 0-100', 20 sx 0-100', 20 sx 1254' 1004-1304', 60 sx Salt: 1237-2344' 2300-2400', 20 sx CIBP, add 10 sx	PLUGGING DATA Surface Plug: Size 100'-Surf. Cemented withsx.