Form 3160-5 .....

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED 135

NM-0766 > it indian. Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

<ul> <li>Type of Well</li> <li>Gas Other</li> <li>Name of Operator</li> <li>ARCO Oild Gas Company</li> <li>Address and Telephone No.</li> <li>P. O. Box 1610, Midland, Texas 73</li> <li>4 Location of Well (Footage, Sec., T. R., M. or Survey Description)</li> <li>990' FNL &amp; 330' FWL (Unit Letter II)</li> </ul>	702-1610 915 688-5672	8. Weil Name and No. South Justis Unit "E" #15 9. API Well No. 30-025-11558 10. Field and Pool. or Exploratory Area Justis Blbry-Tubb-Dkrd 11. County or Pansh. State Lea
Section 13-255-37E		
CHECK APPROPRIATE EOX(s) TO IN	DICATE NATURE OF NOTICE. REP	ORT. OR OTHER DATA
	TYPE OF ACTIO	
Notice of Intent     Subsequent Report     Final Abandonment Notice      I3. Describe Proposed or Completed Operations (Clearity state all pertinent det     give subsurface locations and measured and true vertical deputs for	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Workover wellbore for South Justis Unitality. And give pertinent dates. Including estimated date of state all markers and zones pertunent to this work.)*	Completion or Recompletion Report and Log form.)
Propose to workover wellbore as f 1. POH w/CA 2. Drill out csg to 5991' (TD) 3. Drill new formation from 5991 4. Run OH log 5. Acidize in two stages 6. RIH w/CA		

14. I hereby certity that the foregoing is true and correct Signed Ken W Stomely		Agent			
(This space for Federal or State office use) (ORIG. SGD.) JOE G. LARA Approved by Conditions of approval, if any:	Title	PETROLEUM ENGINEER	Date	6/21/94	

Title 18 U 2. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictutious or traudment statements OF WEREASTORS & IO ANY MALLER WIRE IS NUTACICON

June	1440	

If Unit or CA. Agreement Designation

Budget Bureau No. 1004-01	3
Expires: March 31, 1993	
Lease Designation and Serial No	)

## WORKOVER PROCEDURE

DATE: May 10, 1994

WELL & JOB: SJU E-15 - Deepen and add perts DRILLED: 1959						
LAST WORKOVER: 8/93 Cleaned out junk		nk FIEL	.D: South Jus	stis COUNTY:	COUNTY: Lea County, New Mexico	
BY: D. C. Bretches	<b>TD:</b> 59	92' <b>PBD</b> :	: 5954' E	DATUM: 15' RKB		
CASING: SURFACE: PROD:	<u>SIZE</u> 9-5/8" 7"	<u>WEIGHT</u> 36.0# 20/23#	<u>GRADE</u> J-55 J-55	<u>SET @</u> 852' 5991'	<u>SX_CMT</u> 400 710	TOC Surface 435' (TS)

PERFORATIONS: Blinebry perfs 5075-5686' and Tubb perfs 5806-5890' (Squeezed Paddock perfs 4976-4990')

TUBING:SIZE: 2-3/8" WEIGHT: 4.7 GRADE: J-55 THREAD: EUE AB Mod JOINTS:187 BTM'D @ 5920

**HISTORY AND BACKGROUND:** This well was drilled and completed in 1959 as a dual Blinebry/Paddock producer. The Paddock perforations were later squeezed and Tubb perforations added. The well currently produces from the Tubb and Blinebry zones. In 1993, a workover was performed to remove junk from the well. The wellbore was cleaned out to PBD of 5954' and a 2-3/8" rod pumping completion assembly was run.

SCOPE OF WORK: Pull completion assembly, deepen well to 6250', run open hole logs, acidize open hole and old pertorations, and rerun completion assembly.

## PROCEDURE

\*Prior to MIRU, shoot fluid level of well to determine proper pump spacing for Adaptable Tool.

- 1. MIRU PU. Pull rods and pump. ND THAF. NU BOPE. POH w/ 160 jts 2-3/8" 4.7# J-55 TBG, TAC, 27 jts 2-3/8" TBG, SN. Perf nipple, and MA.
- PU and RIH w/ 6-1/8" drag bit. Adaptable Tool, and 4" DC's on 2-7/8" N-80 WS to ±5954' (Expected PBD). RU power swivel and while pumping 1/4 BPM gelled BW (Vis @ ±30 sec/qt), drill out CSG f/ 5954 to 5991' (TD). Drill new formation with same tool f/ 5992-6250'. POH laying down Adaptable Tool and DC's.
- 3. RU Atlas. Run Spectral GR/Density/CNL/DLL/CAL f/ TD to 5991' (Correlate to Welex Radioactivity log dated 12/27/59). RD Atlas.
- 4. PU and RIH w/ Ret PKR on 2-7/8" WS. Treat Drinkard open hole as per pending treatment procedure. Rise PKR and TOH. TIH w/ RBP and PKR. Treat Tubb/Blinebry perfs as per pending treatment procedure. Rise PKR and RBP. TOH and lay down WS.
- 5. RIH w/ 2-3/8" CA, rods, and pump as per Production Dept. recommendation. RD PU. Clean location. TOTPS

D. C Bretches

J. E. Shields

