

**CARLSON FEDERAL #1
JUSTIS FIELD
LEA COUNTY, NEW MEXICO**

Project Engineer: Blake A. Picquet

Office: (915) 688-6991

Home: (915) 699-3264

RECOMMENDED PLUG AND ABANDON PROCEDURE

**Note: Notify OCD prior to any plugging operations.
H₂S may be present.**

Top of Salt: 1,200'

1. Order out tubing racks and $\pm 3,150'$ of 2 3/8", 4.7#, N-80 workstring.
2. MIRU service unit. ND wellhead. NU BOP.
3. POOH laying down kill string. PU workstring and RIH to tag plug @ 4,569'.
4. Circulate hole with 10.0 ppg gelled mud (25lbs of gel per barrel).
5. PU to $\pm 1,250'$ and spot 7 sx (100') Class C cmt. across the top of salt.
6. PU to 940' and spot 7 sx (100') Class C cmt. across surface casing shoe. Tag top of plug @ 840'.
7. PU to $\pm 140'$ and spot 10 sx Class C cmt. to the surface.
8. ND BOP. RDMO service unit.
9. Cut casing off 3' below surface. Weld steel plate and P&A monument (4" O.D. and 4' above ground level) including operator name, lease name and well number and location, including unit letter, section, township and range. Restore location as directed.

Approved: _____ Date: _____
Hal Lee