Form 3160-5 (December 1989)	UNITED STATES DEPARTMENT OF THE INTERIOR N. M. Cil. CU DUPENING AND MANAGEMENT P. O. BOX 1		Expires September 10, 1990		
e	BUREAU OF _AND MAI	88240 LC-060943			
o not use this form	onder no lices and her for proposals to drill or to deep * "APPLICATION FOR PERMIT-	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
	SUBMIT IN TRIPLI	CATE	7. IF UNIT OR CA, AGREEMENT DESIGNATION		
1. TYPE OF WELL	X WELL GAS OTHER		8. WELL NAME AND NO.		
2. NAME OF OPERATOR ARCO OII & Ga	s Company		South Justis Unit "D" #17 9. API WELL NO. 30-025-11583		
3. ADDRESS AND TELEP	HONE NO.		10. FIELD AND POOL, OR EXPLORATORY AREA		
	Midland, TX 79702	(915) 688-5672	Justis Blbry-Tubb-Dkrd		
4. LOCATION OF WELL	(Footage, Sec., T., R., M., or Survey Descri	ption)	11. COUNTY OR PARISH, STATE		
1650 FSL & 3 14-25S-37E	330 FEL (Unit Letter I)		Lea		
	CK APPROPRIATE BOX(S) TO I	NDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA		
	SUBMISSION		F ACTION		
			CHANGE OF PLANS		
	ICE OF INTENT				
SUB	SEQUENT REPORT		NON-ROUTINE FRACTURING		
FIN	AL ABANDONMENT NOTICE	ALTERING CASING			
. DESCRIBE PROPOSE	D OR COMPLETED OPERATIONS (Clearly	(NOTE: Report Comple	er wellbore for South Justis Unit t results of multiple completion on Well etion or Recompletion Report and Log form.) dates, including estimated date of starting any hs for all markers and zones pertinent to this work.)*		
	rkover well bore for South Justis U		Se 3		
1.	POH w/CA.				
	Cut over & fish Model "D" pkr @	5644.	- (11		
	CO to 6006 PBD.		II 20		
4.	Run csg integrity test.		0 60		
5.	Add perforations and stimulate.				
6.	RIH w/CA.		.		
14. I hereby certify the	hat the foregoing is true and correct				
signed <u>X</u>	en av Losnelf_		DATE9-2-93		
(This space for Fe	deral or State office use)				
	(ORIG. SGD.) IOF G. L	APA DETROLASI	ENGINEER 923/93		
APPROVED BY CONDITIONS FOR	APPROVAL, IF ANY:	TITLE STORY CAN BE AND THE	DATEDATE		
Title 18 U.S.C. Sec fictitious or fraudu	ction 1001, makes it a crime for any per lent statements or representations as to a	son knowingly and willfully to make to any d my matter within its jurisdiction.	department or agency of the United States any false		
		See Instructions on Reverse Side	1-1		

OCD HUBBS

SEP 2 7 1995

RECEIVED

WORKOVER PROCEDUkr

DATE:7/06/93

WELL & JOB: SJU "D" #17 - Clean out to 6006' and bring into unit DRILLED: 1959								
LAST WORKOVER: 9-16-91 - Replace pump				FIELD: South Justis Unit	Unit COUNTY: Lea, NM			
BY: B. G. Voig		TD: 6020'		PBD: 5634'	DATUM: 13' R	KB		
TUBINGHEAD:	?		SIZE:		PRESS RATIN	G:		
CASING: SURFACE:	<u>SIZE</u> 9-5/8"	<u>WEIGHT</u> 32.3 lb	<u>GRADE</u> H-40	<u>SET @</u> 899'	<u>SX CMT</u> 407 sx	TOC circ.		
INTER: PROD:	7"	20 & 23 lb	J-55	6016'	751 sx	1700' (TS)		
LINER:	SIZE	WEGHT	<u>GRADE</u>	TOP	<u>BTM</u>	<u>TO</u>		

PERFORATIONS: Blinebry: 5093, 5104, 11, 16, 20, 37, 41, 48, 75, 81, 5200, 20, 43, 53, & 5404-20' (4JSPF) Tubb/Drinkard: 5788-97, 5805-12, 5838-44, 5860-67, 5914-22, 5930-40, 5952-60, & 5962-71' at 2 JSPF (PA'd by setting DR plug in Model "D" pkr at 5644' and dumping 2 sx cmt on top on 5-19-65)

TUBING:	SIZE: 2-3/8"	v	WEIGHT: 4.7	GIELDER 7 55	THREAD: Buttres
BTM'D @ 5360'		JOINTS:		MISC: 1 jt 2-3/8" EUE 8rd J-55 tbg SN, SN at 5320' as of 2-6-7	

PACKER AND MISC: Fish: Baker Model 415-D packer at 5644 w/ DR plug in place and 10' cement on top.

HISTORY AND BACKGROUND: This well was originally drilled as a dual producer in the Blinebry and Tubb/Drinkard zones. Both zones were acidized and fraced. In May of 1965, the Tubb/Drinkard zone was PA'd by placing a DR plug in the Model "D" packer at 5644' and dumping 2 sx of cement on top of the packer. From that point, the well has been producing from the Blinebry zone.

SCOPE OF WORK: Clean well out to original PBD of 6006' and bring into unit

PROCEDURE

- MIRU PU. POOH with rods and pump. ND WLHD. NU BOP. POOH with completion assembly. 1.
- RIH with 6-1/4" MT bit and DC's on 2-7/8" WS to top of Blinebry perforations at 5093'. Break 2. circulation using bridging material. Continue in hole and clean out to top of packer at 5644'. Circulate hole clean and POOH.
- RIH with 6-1/8" x 4-5/8" cut-rite shoe and washover assembly on 2-7/8" WS. Cut over Baker 3. Model "D" packer at 5644'. Clean well out to 6006'. Attempt to jam fish in washpipe. Circulate hole clean and POOH with fish.
- RIH with Baker Model "G" RBP on WS and set at 5050'. Conduct casing integrity test to 500 psi. 4 Retrieve RBP and POOH.
- Add perforations and stimulate.
 - RIH with completion assembly per F/P Engineering design. ND BOP. NU WLHD. RIH with pump and 5. rods per F/P Engineering design.
 - 6. RD PU. TOTPS.

Permian Team Drilling Engineer

raian Drilling Team Leader

OFFICE

AET 2 1993

RECEIVED

.



DE RUDOS DEFIOS

4-12 391