

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-11844

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER ☐

2. Name of Operator

Meridian Oil Inc.

3. Address of Operator

P.O. Box 51810, Midland, TX 79710-1810

4. Well Location

Unit Letter 0 : 660 Feet From The S Line and 1980 Feet From The E Line

Section 30 Township 25S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


1. Notify OCD prior to starting work. MIRU PU. Kill well if necessary. POOH w/rods laying down. ND WH, NU BOP. POOH w/tubing laying down. Pick up workstring and RIH w/casing scraper to +3090', POOH. Set cement retainer on tubing at +3085'. Squeeze under retainer w/25 sxs of cement. Sting out of retainer and spot a cement plug across the base of the salt at 2565 to 3090'. Use 55 sxs of cement. Pull up above plug and circulate hole w/9ppg gelled brine.

2. Pull tp to 1255' and spot a cement plug across the top of the salt at 1135 to 1255' using 15 sxs of cement. Pull up to 370' and circulate cement to surface using 40 sxs of cement. POOH laying down workstring. ND BOP, RDMO PU. Cut off casing 3' below ground level and install a P & A marker.

3. Clear, rip, and reseed location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE

Production Assistant

DATE 1-4-93

TYPE OR PRINT NAME

Donna J. Williams

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

APPROVED BY

TITLE

DATE

JAN - 8 1993

CONDITIONS OF APPROVAL, IF ANY: